

Commercial Vehicle **Inspection Report**

Decal Number: **Decal Expiry Date:** Inspection Number: G154453 2025-Nov-30 21333969

Inspection Result:

NSPECTOR:

FACILITY:

H. A. MECHANICAL & WELDING /

NORK ORDER #:

AIKEMA, HARLEY / 101034

INSP. REASON:

INSP. TYPE: INSP. CLASS:

Class 2 - Heavy Vehicle with LGVW INSP. COMPLETE:

INSP. START:

2025-Apr-29 11:32 AM PDT

ADDRESS:

2025-May-01 10:32 AM PDT

5501 kg or more Semi-annual

Complete

12736049

Truck Tractor

838673 Miles

1309

/EHICLE JUR:

/EHICLE YEAR:

British Columbia

76898P

JCENCED GVW(kg): 47000 2016

VIAKE: WODEL:

PLATE #:

KENWORTH

REGI-UNIT/FLEET#:

BODY STYLE: ODOMETER:

HUB ODOMETER: **BRAKE TYPE:**

Air **FUEL TYPE:** Diesel

1XKYD49X2GJ981309 VIN: OWNER/LESSEE NAME

Vehicle Identification (VIN)

Section 1 - Power Train

Section 2 - Suspension

Section 3 - Brake System

Section 3A - Air Brakes Section 3H - Hydraulic Brakes

Section 4 - Steering Section 5 - Instruments and Auxiliary

Equipment

Section 6 - Lamps

Section 7 - Electrical System

Section 8 - Frame and Body Section 9A - Tires

Section 9B - Wheels Section 10 - Coupling Devices

Section 11 - Other Vehicle Components

Passed Passed

Passed

Passed

Passed

Passed

Passed

Passed

Passed

Not Applicable

Repaired (same day)

DRIVE AXLE BUSHINGS Not Applicable

Repaired (same day) Not Applicable

Tire Tread Depth (mm)

Left

20

16

15

3RD AXLE SLACK & BRAKEPOTS 2ND RIGHT POT

Repaired (same day) SEVERAL LIGHTS OUT

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles Туре Size Slack Adi. 1 aft Right Clamp 24L Automatic 32 32 Clamp 30L Automatic 34 34 2 Automatic 34 34 Clamp 301 3

Inner R Outer L Inner L 10 15 14 10 11 Comment:

Right

19

14

14

9 13 13 8 9

Outer R

Steering

Right

Air Brake Camshaft Rotation (degrees)

Axles

2

3

Comment:

Comment:

Left Right 35 35 45 65 55 75

Lining (Shoe)

Brake Lining/Pad (mm)

Lining (Shoe) Lining (Shoe) Comment:

Lining/Pad

Rotor Thickness or Drum Inside Diameter (mm) Rotor/Drum Left

Drum Drum Drum

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

nspection Comments:

nspector:

AIKEMA, HARLEY

las this Vehicle been road tested?

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-01 10:36 AM PDT

The inspector's signature above is certification that this vehicle has been inspected to the requir ents of the Motor Vehicle Act and Regulations.

NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations, It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement