



Commercial Vehicle Inspection Report

Decal Number: GJ19346
Decal Expiry Date: 2026-May-31
Inspection Number: 21359421

Inspection Result: **PASS** 109-6

ACILITY:	J & G FLEET SERVICES LTD / S16741	INSP. TYPE:	Complete	INSP. START:	2025-May-21 01:00 PM PDT
INSPECTOR:	PAISLEY, ETHAN / 301284	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-May-22 07:23 AM PDT
WORK ORDER #:	19106	INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	02966686	VIN:	2B925TT3351005066
LATE #:	11140D	UNIT/FLEET#:	E284	OWNER/LESSEE NAME:	KLAASSEN EQUIPMENT LTD., KLAASSEN EQUIPMENT LTD.
PERMITTED GVW(kg):	999999	BODY STYLE:	Flat Deck Trailer	ADDRESS:	8-6014 VEDDER ROAD
VEHICLE YEAR:	2005	ODOMETER:			Chilliwack, British Columbia
MAKE:	BWS	HUB ODOMETER:			V2R5P5, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACED #1R SLACK ADJUSTER, REPLACED GLADHAND SEALS
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) REPLACED DAMAGED REFLECTIVE TAPE
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	42	45	9	10	7	8	
2	Clamp	30	Automatic	39	40	8	11	8	10	
3	Clamp	30	Automatic	44	42	8	8	10	10	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	90	80	Lining (Shoe)	13	16	Drum		
2	65	60	Lining (Shoe)	19	18	Drum		
3	60	90	Lining (Shoe)	17	15	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Ethan Paisley Road Tester:

Inspector: PAISLEY, ETHAN Signature:

This Inspection Report was submitted to CVSE on 2025-May-22 07:26 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.