

FACILITY: GEMM DESIG LTD. / 53195	INSR TYPE: Complete	INSR START: 2025-Sep-16 08:54 AM PDT
INSPECTOR: Botnikoff, Sturlin / 300656	INSR CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSR COMPLETE: 2025-Sep-16 10:54 AM PDT
WORK ORDER #: W79333	INSR REASON: Semi-annual	

VEHICLE JUR: Saskatchewan	REG:	VIN: FVDE40PEY289502
PLATE #:	UNIT/FLEET#:	OWNER/LESSEE NAME: LTD., J.C. LAND & LIVESTOCK
LICENCED GVW(kg): 46500	BODY STYLE: Tractor	ADDRESS: P.O. BOX 519
VEHICLE YEAR: 2000	ODOMETER: 257657 KM	Delisle, Saskatchewan
MAKE: VOLVO	HUB ODOMETER:	S0LPS, Canada
MODEL:	BRAKE TYPE: Air	
	FUEL TYPE: Diesel	

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) #3 ALE BRAKES CHANGED, #3L BRAKE CHANGED.
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) STEERING U-JOINT CHANGED.
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				Steering
Axles	Type	Size	Stack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	
1	Clamp	24	Automatic	40	35	12			12	✓
2	Clamp	30	Automatic	45	45	20	21	20	21	
3	Clamp	30	Automatic	45	30	21	19	20	20	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Left	Right	Left	Right	Rotor/Drum	Left	Right
1	45	45	Lining (Shoe)	16	17		Drum		
2	30	90	Lining (Shoe)	17	12		Drum		
3	30	30	Lining (Shoe)	17	17		Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? ☒ No **Road Test Date:** **Road Tester:**

Inspector: Botnikoff, Sturlin **Signature:**

This Inspection Report was submitted to CVSE on 2025-Sep-16 10:54 AM PDT.
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.