



Commercial Vehicle Inspection Report

Decal Number: GJ34231
 Decal Expiry Date: 2026-Jun-30
 Inspection Number: 21362166

Inspection Result:
PASS

FACILITY: Royal Truck Repair LTD. / 820446 **INSR TYPE:** Complete **INSR START:** 2025-Jun-06 03:00 PM PDT
INSPECTOR: Sidhu, Navjot Singh / 200067 **INSR CLASS:** Class 3 - Trailer and Semi-Trailer **INSR COMPLETE:** 2025-Jun-06 04:00 PM PDT
WORK ORDER #: **INSR REASON:** Annual

VEHICLE JUR: British Columbia **REGI:** 00418240 **VIN:** 1GRAA06288W700286
PLATE #: 92258K **UNIT/FLEET#:** 59198 **OWNER/LESSEE NAME:** BOBBY'S, TRANSPORT LTD
LICENCED GVW(kg): 999999 **BODY STYLE:** Reefer Van Trailer **ADDRESS:** 6936 PRINCE EDWARD ST
VEHICLE YEAR: 2006 **ODOMETER:** **Vanouver, British Columbia**
MAKE: GREAT DANE **HUB ODOMETER:** **V5XG3, Canada**
MODEL: **BRAKE TYPE:** Air **FUEL TYPE:**

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) 1XL L/S BRAKE CHAMBER FITTING CHANGE
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axis	Type	Size	Stack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	36	36	6	6	14	14	
2	Clamp	30	Automatic	36	36	6	9	9	6	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)


Axis	Left Rotation (degrees)		Right Rotation (degrees)		Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
	Left	Right	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	48	47	47	47	Lining (Shoe)	17	17	Drum		
2	62	48	48	48	Lining (Shoe)	16	17	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Read Test Date:** **Inspector:** Sidhu, Navjot Singh **Signature:**  **Road Tester:**

This Inspection Report was submitted to CVSE on 2025-Jun-06 07:56 PM PDT. The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 210 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the B.C. Manager, NSQVIP at the Commercial Vehicle Safety Enforcement.

CVSE014
 06/02/25 7:06:50 PM PDT