

V11-2



BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Docal Number: GJ34118
Decal Expiry Date: 2026-Apr-30
Inspection Number: 21301154

Inspection Result:
PASS

FACILITY: Royal Truck Repair LTD. / S20445 **INSR TYPE:** Complete
INSPECTOR: Sidhu, Navjot Singh / 200057 **INSR CLASS:** Class 3 - Trailer and Semi-Trailer
WORK ORDER #: **INSR REASON:** Annual
INSR. START: 2025-Apr-04 08:30 AM PDT
INSR. COMPLETE: 2025-Apr-04 10:35 AM PDT

VEHICLE JUR: British Columbia **REG#:** 03687772 **VIN:** 1UYV928347U860118
PLATE #: 47887K **UNIT/FLEET#:** 58707 **OWNER/LESSEE NAME:** BOBBY'S , TRANSPORT LTD
LICENSED GVM(kg): 999999 **BODY STYLE:** Van Trailer **ADDRESS:** 6936 PRINCE EDWARD ST
VEHICLE YEAR: 2007 **ODOMETER:** Vancouver, British Columbia
MAKE: UTLITY **HUB ODOMETER:** V5XGP3, Canada
MODEL: **BRAKE TYPE:** Air
 FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) BACK SIDE DOOR LOCK FIXED
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)					Steering	
Axes	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	32	34	15	15	12	11	
2	Clamp	30	Automatic	34	34	13	14	11	9	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axes	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	45	47	Lining (Shoe)	16	16	Drum		
2	36	35	Lining (Shoe)	18	18	Drum		
Comment:			Comment:		Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**
Inspector: Sidhu, Navjot Singh **Signature:** 

This Inspection Report was submitted to CVSE on 2025-Apr-04 05:48 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 119 of the Motor Vehicle Act and Division 29 of the Motor Vehicle Act (Regulation). It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. registering carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection or use of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement.

CVSEB014

4/4/2025 6:48:06 PM PDT