



BRITISH COLUMBIA

# Commercial Vehicle Inspection Report

Decal Number: GB76530  
Decal Expiry Date: 2024-Sep-30  
Inspection Number: 20852355

VI Inspection Result  
**PASS**

FACILITY: A & K DIESEL REPAIR LTD. / S4438 INSP. TYPE: Complete INSP. START: 2024-Mar-13 10:15 AM PDT  
INSPECTOR: SAHOTA, HARDEEP SINGH / 114246 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2024-Mar-13 11:30 AM PDT  
WORK ORDER #: INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 02526297 VIN: 2B9KSBA84B304632  
PLATE #: 96138U UNIT/FLEET#: 17 OWNER/LESSEE NAME: SP EARTH MOVERS LTD.,  
LICENSED GVW(kg): 999999 BODY STYLE: Pup Trailer ADDRESS: 18758 54 AVE  
VEHICLE YEAR: 2004 ODOMETER: Surrey, British Columbia  
MAKE: BRENTWOOD HUB ODOMETER: V3S 2H6, Canada  
MODEL: BRAKE TYPE: Air  
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

### Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	31	31
2	Clamp	30	Automatic	31	31

Comment:

### Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
10	11	15	13	
13	14	16	14	

Comment:

### Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	55
2	50	64

Comment:

### Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	16
Lining (Shoe)	16	15

Comment:

### Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

### Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:  
Inspector: SAHOTA, HARDEEP SINGH Signature: *Hardeep S. Sahota*

This Inspection Report was submitted to CVSE on 2024-Mar-13 01:45 PM PDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

3/13/2024 1:45:22 PM PDT