



Commercial Vehicle Inspection Report

Decal Number: GM42528
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21633117

Inspection Result: **PASS**

VLE

FACILITY: SPEED TRUCK & TRAILER REPAIR (ABBY) LTD. / S20520
INSPECTOR: Auja, Gagandeep / 300544
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Jan-16 06:00 PM PST
INSP. COMPLETE: 2026-Jan-16 08:00 PM PST

VEHICLE JUR: British Columbia
PLATE #: W85163
LICENCED GVW(kg): 44000
VEHICLE YEAR: 2005
MAKE: STERLING
MODEL:

REGI: 02368899
UNIT/FLEET#: 3
BODY STYLE: Dump Truck
ODOMETER: 93470 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2FZHAZCV75AN73505
OWNER/LESSEE NAME: SP EARTH MOVERS LTD...
ADDRESS: 18758 54 AVE
Surrey, British Columbia
V3S2H6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxillary Equipment	Passed
Section 6 - Lamps	Repaired (same day) SIGNALS REPAIRED
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) TIRE REPLACED
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automstic	32	32	6			12	✓
2	Clamp	30L	Automatic	35	35	11	4	14	14	
3	Clamp	30L	Automatic	35	35	9	11	6	8	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	52	52	Lining (Shoe)	17	17	Drum		
2	50	50	Lining (Shoe)	17	17	Drum		
3	55	55	Lining (Shoe)	15	15	Drum		

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: Auja, Gagandeep
Road Test Date:
Signature: 
Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jan-16 10:14 PMPST
The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.