



Commercial Vehicle Inspection Report

Decal Number: GM42528
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21633117

Inspection Result:
PASS

FACILITY: SPEED TRUCK & TRAILER REPAIR (ABBY) LTD. / S20520	INSR. TYPE: Complete	INSR. START: 2026-Jan-16 06:00 PM PST
INSPECTOR: Aujja, Gagandeep / 300544	INSR. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSR. COMPLETE: 2026-Jan-16 08:00 PM PST
WORK ORDER #:	INSR. REASON: Semi-annual	

VEHICLE JUR: British Columbia	REGI: 02368899	VIN: 2FZHACV75AN73505
PLATE #: WBS163	UNIT/FLEET#: 3	OWNER/LESSEE NAME: SP EARTH MOVERS LTD., .
LICENCED GWW(kg): 44000	BODY STYLE: Dump Truck	ADDRESS: 18758 54 AVE
VEHICLE YEAR: 2005	ODOMETER: 93470 KM	Surrey, British Columbia
MAKE: STERLING	HUB ODOMETER:	V3S2H6, Canada
MODEL:	BRAKE TYPE: Air	
	FUEL TYPE:	

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) SIGNALS REPAIRED
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) TIRE REPLACED
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axes	Type	Size	Stack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	32	32	9			12	✓
2	Clamp	30L	Automatic	35	35	11	4	14	14	
3	Clamp	30L	Automatic	35	35	9	11	6	8	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axes	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	52	52	Lining (Shoe)	17	17	Drum		
2	50	50	Lining (Shoe)	17	17	Drum		
3	55	55	Lining (Shoe)	15	15	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
 Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**
Inspector: Aujja, Gagandeep **Signature:** _____

This inspection report was submitted to CVSE on 2026-Jan-16 10:14 PMPST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCOVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

1/16/2026 10:14:28 PM PST