

FACILITY:	Smith Tank & Trailer Repair - Nanaimo / S20317	INSP. TYPE:	Complete	INSP. START:	2025-Jun-13 01:03 PM PDT
INSPECTOR:	WEATHERILL, DANE / 300297	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-Jun-13 03:04 PM PDT
WORK ORDER #:		INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	01070063	VIN:	2C9LBA2R071026082
PLATE #:	45674K	UNIT/FLEET#:	721	OWNER/LESSEE NAME:	bridgeway transport ltd, bridgeway transport ltd
LICENCED GVW(kg):	999999	BODY STYLE:	Tank Trailer	ADDRESS:	9467 195 st
VEHICLE YEAR:	2007	ODOMETER:			Surrey, British Columbia
MAKE:	COLUMBIA R	HUB ODOMETER:	177033 KM		v4n 4g3, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) 3l air bag cords showing, 1r 2l shocks leaking
Section 3 - Brake System	Repaired (same day) 2l drum wore out, 2l brake chamber broken spring, 1r slack adjuster out of adjustment.
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed with Caution frame corrosion.
Section 9A - Tires	Repaired (same day) 3l tire wore out new tire installed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	30	30	4	4	4	4	
2	Clamp	30	Automatic	30	30	5	5	5	5	
3	Clamp	30	Automatic	30	30	4	4	6	5	
Comment:						Comment: 3l inner outer tires replaced				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	85	75	Lining (Shoe)	13	14	Drum		
2	30	30	Lining (Shoe)	19	19	Drum		
3	50	60	Lining (Shoe)	18	17	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:**  **Road Tester:**

Inspector: WEATHERILL, DANE **Signature:**

This Inspection Report was submitted to CVSE on 2025-Jun-13 03:04 PMPDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

