



Commercial Vehicle Inspection Report

Decal Number: GD90499
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21135047

Inspection Result:

PASS

FACILITY:	LIGHTHOUSE MECHANICAL / 56863	INSP. TYPE:	Complete	INSP. START:	2024-Nov-04 11:45 AM PST
INSPECTOR:	DYCK, ALLAN TRENT / 113057	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2024-Nov-04 02:00 PM PST
WORK ORDER #:		INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	0070493	VIN:	5V8VA53B17M708884
PLATE #:	90070B	UNIT/FLEET#:	533V263	OWNER/LESSEE NAME:	Comox Valley, Distribution Ltd.
LICENCED GVW(kg):	999999	BODY STYLE:	Van Trailer	ADDRESS:	11398 Bridgeview Drive, 11398 Bridgeview Drive Surrey, British Columbia V3R0C2, Canada
VEHICLE YEAR:	2007	ODOMETER:			
MAKE:	VANGUARD	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) Replace #2 LH shoes and hardware, Replace #3 RH Piggyback
Section 3A - Air Brakes	Repaired (same day) Replace #2 LH shoes and hardware, Replace #3 RH Piggyback
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) Repair roof leak
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	33	30
2	Clamp	30	Automatic	32	33
3	Clamp	30	Automatic	33	35

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
10	5	4.6	6.4	
13	13	13	14	
10	9	5	7.9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	48	46
2	82	74
3	37	33

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	17
Lining (Shoe)	13	16
Lining (Shoe)	18	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	420.37	0.00
Drum	0.00	0.00

Comment: Only #2 LH removed

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: DYCK, ALLAN TRENT

Road Test Date:
Signature:

Allan Dyck

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Nov-06 11:03 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/V/P at the Commercial Vehicle Safety Enforcement.

CVSE0014

11/6/2024 11:03:52 AM PST

