



# Commercial Vehicle Inspection Report

Decal Number: GL32066  
Decal Expiry Date: 2026-Dec-31  
Inspection Number: 21598698

W04-1  
Inspection Result:  
**PASS**

**FACILITY:** P & R TRUCK CENTRE LTD. / S20272      **INSP. TYPE:** Complete      **INSP. START:** 2025-Dec-10 09:30 AM PST  
**INSPECTOR:** TAYLOR, RICHARD WILLIAM ROBERT / 107281      **INSP. CLASS:** Class 3 - Trailer and Semi-Trailer      **INSP. COMPLETE:** 2025-Dec-10 11:00 AM PST  
**WORK ORDER #:** 4646

**VEHICLE JUR:** British Columbia      **REGI:** 13372177      **VIN:** 2A9PF4532TN125255  
**PLATE #:** A1D2R5      **UNIT/FLEET#:**      **OWNER/LESSEE NAME:** RAMIDA ENTERPRISES, LTD  
**LICENCED GVW(kg):** 0      **BODY STYLE:** Flat Deck Trailer      **ADDRESS:** 7007 EAST SOOKE RD  
**VEHICLE YEAR:** 1996      **ODOMETER:**      **Sooke, British Columbia**  
**MAKE:** GERRYS      **HUB ODOMETER:**      **V9Z1A8, Canada**  
**MODEL:**      **BRAKE TYPE:** Air      **FUEL TYPE:**

<b>Vehicle Identification (VIN)</b>	Passed
<b>Section 1 - Power Train</b>	Not Applicable
<b>Section 2 - Suspension</b>	Passed
<b>Section 3 - Brake System</b>	<b>Repaired (same day)</b> <b>STROKE INDICATORS</b>
<b>Section 3A - Air Brakes</b>	Passed
<b>Section 3H - Hydraulic Brakes</b>	Not Applicable
<b>Section 4 - Steering</b>	Not Applicable
<b>Section 5 - Instruments and Auxiliary Equipment</b>	Passed
<b>Section 6 - Lamps</b>	Passed
<b>Section 7 - Electrical System</b>	Passed
<b>Section 8 - Frame and Body</b>	Passed
<b>Section 9A - Tires</b>	Passed
<b>Section 9B - Wheels</b>	Passed
<b>Section 10 - Coupling Devices</b>	Passed
<b>Section 11 - Other Vehicle Components</b>	Not Applicable

#### Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Tire Tread Depth (mm)					
				Left	Right	Outer L	Inner L		
1	Clamp	30	Automatic	38	38	8	10	16	11
2	Clamp	30	Automatic	38	38	16	13	8	8
3	Clamp	30	Automatic	38	38	10	10	11	10

Comment:

Comment:

#### Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)				Rotor Thickness or Drum Inside Diameter (mm)		
			Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	90	45	Lining (Shoe)	12	17	Drum			
2	70	70	Lining (Shoe)	14	14	Drum			
3	75	75	Lining (Shoe)	14	14	Drum			

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

#### Inspection Comments:

Has this Vehicle been road tested?  No      Road Test Date: *10/10/2025*      Road Tester: *Richard Taylor*  
 Inspector: TAYLOR, RICHARD WILLIAM ROBERT      Signature: *Richard Taylor*

This Inspection Report was submitted to CVSE on 2025-Dec-10 11:51 AM PST  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement.

CVSE0014

12/10/2025 11:51:51 AM PST