

Commercial Vehicle COLUMBIA Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number:

GJ04746 2026-May-31 21561117

Inspection Result: PASS

FACILITY: INSPECTOR: TRIPLE 8 INSPECTIONS / S14290

INSP. CLASS:

Complete

INSP. START: INSP. COMPLETE: 2025-Nov-07 01:30 PM PST

COOKSON, MICHAEL GWYLLUM /

Class 2 - Heavy Vehicle with LGVW 5501 kg or more

2025-Nov-07 03:00 PM PST

WORK ORDER #: VEHICLE JUR:

INSP. REASON:

UNIT/FLEET#:

REGI:

Semi-annual

12598631

British Columbia WK1732

LICENCED GVW(kg): 39500 VEHICLE YEAR: 2019

BODY STYLE: ODOMETER:

Truck Tractor 1341863 KM

712

VIN: OWNER/LESSEE NAME:

ADDRESS:

3AKJHHDR2KSKA3079 TRIPLE EIGHT, TRANSPORT INC

30697 MARSHALL ROAD Abbotsford, British Columbia

V2T6J7, Canada

MAKE: MODEL:

PLATE #:

FREIGHTLIN

BRAKE TYPE: Air

FUEL TYPE:

Vehicle Identification (VIN) Section 1 - Power Train

Section 2 - Suspension Section 3 - Brake System

Section 3A - Air Brakes Section 3H - Hydraulic Brakes

Section 4 - Steering Section 5 - Instruments and Auxiliary

Equipment Section 6 - Lamps Section 7 - Electrical System Section 8 - Frame and Body

Section 9A - Tires Section 9B - Wheels Section 10 - Coupling Devices

Section 11 - Other Vehicle Components

HUB ODOMETER:

REPLACED SLACK ADJUSTERS #3 AXLE. REPLACED BRAKE CHAMBER #2 AXLE L/S. Repaired (same day)

Passed Not Applicable Passed

Passed

Passed

Passed

Passed Passed Passed Passed Passed

Passed

Repaired (same day)

Passed

| Air Brake Cha | mber Type, S | ize and Pusi | h Rod Stroke (mm) | | | Tire Tread Dept | h (mm) | | | |
|---------------|--------------|--------------|-------------------|------|-------|-----------------|---------|---------|---------|-------------|
| Axles | Type | Size | Slack Adj. | Left | Right | Outer L | Inner L | Inner R | Outer R | Steering |
| 1 | Clamp | 24 | Automatic | 30 | 42 | 14.3 | | | 13.5 | ~ |
| 2 | Clamp | 30L | Automatic | 48 | 40 | 8.7 | 6.4 | 8.7 | 6.4 | |
| 3 | Clamp | 30L | Automatic | 61 | 61 | 7.9 | 7.1 | 10.3 | 9.5 | is a second |
| Comment: | | | | | | Comment: | | | | (41) |

ADJUSTED 5TH WHEEL

| Air Brake Camshaf | t Rotation (degr | ees) | Brake Lining/Pad (mm) | | Rotor Thickness or Drum Inside Diameter (mm) | | | | |
|-------------------|------------------|-------|-----------------------|------|--|---|------|-------|--|
| Axles | Left | Right | Lining/Pad | Left | Right | Rotor/Drum | Left | Right | |
| 1 | 31 | 60 | Lining (Shoe) | 19 | 16 | Drum | | | |
| 2 | 30 | 30 | Lining (Shoe) | 19 | 19 | Drum | | | |
| 3 | 32 | 37 | Lining (Shoe) | 19 | 18 | Drum | | | |
| Comment: | | | Comment: | | | Comment: Air Brake Camshaft Rotation performed. Rotor | | | |

Inspection Comments:

Has this Vehicle been road tested? COOKSON, MICHAEL GWYLLUM Inspector:

Road Test Date: Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Nov-07 03:27 PM PST

No

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations, it is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement CVSE0014

11/7/2025 3:27:51 PM PST