



Commercial Vehicle Inspection Report

Decal Number: GD63237
Decal Expiry Date: 2025-Mar-31
Inspection Number: 21070290

Inspection Result: ^{X/4}
PASS

FACILITY: PENSKE TRUCK LEASING / S5241 **INSP. TYPE:** Complete **INSP. START:** 2024-Sep-12 05:00 PM PDT
INSPECTOR: BUSTAMANTE, DANILO / 301022 **INSP. CLASS:** Class 2 - Heavy Vehicle with LGVV 5501 kg or more **INSP. COMPLETE:** 2024-Sep-12 06:26 PM PDT
WORK ORDER #: 2206-242007 **INSP. REASON:** Semi-annual

VEHICLE JUR: British Columbia **REGI:** 12919137 **VIN:** 4V4NC9TK6KN239867
PLATE #: NJ3666 **UNIT/FLEET#:** 619678 **OWNER/LESSEE NAME:** GORDON FOOD SERVICE CANADA, GORDON
PERMITTED GVW(kg): 47500 **BODY STYLE:** Truck Tractor **ADDRESS:** 1700 CLMEDEN AVE.
VEHICLE YEAR: 2019 **ODOMETER:** 737546 KM **Delta, British Columbia**
MAKE: VOLVO **HUB ODOMETER:** **V3M6T2, Canada**
MODEL: **BRAKE TYPE:** Air
FUEL TYPE: Diesel

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxillary Equipment	Passed
Section 6 - Lamps	Repaired (same day) replaced top left clearance light
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) replaced right steer tire
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	25.4	31.8	10.3			12.7	✓
2	Clamp	30L	Automatic	38.1	31.8	11.1	9.5	11.1	11.9	
3	Clamp	30L	Automatic	31.8	38.1	15.1	8.7	8.7	10.3	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	75	60	Lining (Shoe)	16	15	Drum		
2	80	80	Lining (Shoe)	14	16	Drum		
3	60	80	Lining (Shoe)	16	16	Drum		

Inspection Comments:
Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**
Inspector: BUSTAMANTE, DANILO **Signature:**

This Inspection Report was submitted to CVSE on 2024-Sep-12 06:31 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement