

X17-



Commercial Vehicle Inspection Report

Decal Number: GM54899
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21689025

Inspection Result:
PASS

FACILITY:	SARABHA TRUCK REPAIR SERVICES LTD. / S20381	INSP. TYPE:	Complete	INSP. START:	2026-Mar-08 08:00 AM PST
INSPECTOR:	BRING, GURMAN SINGH / 300243	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Mar-08 10:00 AM PST
WORK ORDER #:		INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	11896460	VIN:	4V4NC9EJ7AN288327
PLATE #:	A2A3R2	UNIT/FLEET#:	L102	OWNER/LESSEE NAME:	SARABHA TRANSPORT LTD.,
LICENCED GVW(kg):	47000	BODY STYLE:	Truck Tractor	ADDRESS:	8891 218 ST., Langley BC V1M4B9
VEHICLE YEAR:	2010	ODOMETER:	1471824 KM		Langley, British Columbia
MAKE:	VOLVO	HUB ODOMETER:			V2Y 0W0, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	REPLACE ALL REAR 8 TIRES
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	32	36	9			9	✓
2	Clamp	30L	Automatic	38	39	5	6	4	6	
3	Clamp	30L	Automatic	37	36	5	5	4	5	

Comment: Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	70	70	Lining (Shoe)	14	14	Drum		
2	75	75	Lining (Shoe)	14	14	Drum		
3	78	75	Lining (Shoe)	14	14	Drum		

Comment: Comment: Air Brake Camshaft Rotation performed, Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
 Has this Vehicle been road tested? No Road Test Date: Road Tester:
 Inspector: BRING, GURMAN SINGH Signature: *Bring Gurman Singh*

This Inspection Report was submitted to CVSE on 2026-Mar-07 05:05 PM PST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSICVP at the Commercial Vehicle Safety Enforcement
 CVSE014
 3/7/2026 5:05:06 PM PST