



Commercial Vehicle Inspection Report

Decal Number: GK38896
Decal Expiry Date: 2026-Dec-31
Inspection Number: 21813021

Inspection Result: **PASS** Y05-

FACILITY: OK TIRE COMMERCIAL / S15520 **INSP. TYPE:** Complete **INSP. START:** 2026-Jun-03 09:30 PM PDT
INSPECTOR: Whitson, David Norman / 110985 **INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more **INSP. COMPLETE:** 2026-Jun-15 01:45 PM PDT
WORK ORDER #: IN020372 **INSP. REASON:** Semi-annual

VEHICLE JUR: British Columbia **REGI:** 12628275 **VIN:** 3HAMKTAR4JL424257
PLATE #: MN8352 **UNIT/FLEET#:** **OWNER/LESSEE NAME:** Thompson-nicola Regional Div, THOMPSON-NICOLA
LICENCED GVW(kg): 21500 **BODY STYLE:** BOOKMOBILE **ADDRESS:** 300-465 VICTORIA ST, 300-465 VICTORIA ST
Kamloops, British Columbia
VEHICLE YEAR: 2018 **ODOMETER:** 202569 KM **HUB ODOMETER:** V2C 2A9, Canada
MAKE: INTERNATNA **BRAKE TYPE:** Air
MODEL: **FUEL TYPE:**

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) L/R AIR BAG REPLACED (DRY ROT)
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) leaking qr valve replaced
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) PLATE / MARKER LAMP REPAIRED
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	28.6	28.6	13.5			11.9	✓
2	Clamp	30L	Automatic	34.9	34.9	18.3	20.6	19.1	19.8	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	33	33	Lining (Shoe)	17	17	Drum		
2	30	24	Lining (Shoe)	18	19	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**
Inspector: Whitson, David Norman **Signature:** *David Whitson*

This Inspection Report was submitted to CVSE on 2026-Jun-15 02:11 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.