



Commercial Vehicle Inspection Report

Decal Number: **GM09541**
 Decal Expiry Date: **2026-Jun-30**
 Inspection Number: **21589284**

Inspection Result:
PASS

416-1

FACILITY: FREEWAY HEAVY DUTY SER / S3097
INSPECTOR: TOOR, SURJIT SINGH / 108650
WORK ORDER #: 102690
INSPECTION TYPE: Complete
INSPECTION CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSPECTION REASON: Semi-annual
INSPECTION START: 2025-Dec-02 08:00 AM PST
INSPECTION COMPLETE: 2025-Dec-02 10:00 AM PST

VEHICLE JUR: British Columbia
PLATE #: G63401
REGISTERED GVW(kg): 39500
VEHICLE YEAR: 2009
MAKE: FREIGHTLIN
MODEL:

REGI: 12079047
UNIT/FLEET#:
BODY STYLE: Truck Tractor
ODOMETER: 248005 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1FUJA6CK69LAF8411
OWNER/LESSEE NAME: COAST CRANBERRIES LTD., COAST CRANBERRIES LTD.
ADDRESS: 21710 ALLARD CRES, 21710 ALLARD CRES, 21710 ALLARD CRES
 Langley, British Columbia
 V1M 3W1, Canada

Vehicle Identification (VIN)	Result	Comments
Section 1 - Power Train	Repaired (same day)	- REPAIR FOR "CHECK ENGINE" LIGHT "ON" - SECURE TRANSMISSION OIL LINES FROM RUBBING
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	- REPLACE LEAKING TRACTOR PROTECTION VALVE
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	- REPLACE L/S REAR MARKER/SIGNAL LIGHT
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	- SECURE LOOSE L/S STEPS AT FUEL TANK - REPLACE REFLECTOR MISSING AT REAR OF CAB - REPLACE L/S CAB SHOCK
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed with Caution	- CHECK AND ADJUST 5TH WHEEL
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Stack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	35	35	8.4			8.4	✓
2	Clamp	30L	Automatic	38	38	16.7	16.7	16.7	16.7	
3	Clamp	30L	Automatic	38	38	7.9	8.7	8.7	8.7	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	25	30	Lining (Shoe)	17	17	Drum		
2	30	30	Lining (Shoe)	18	18	Drum		
3	35	30	Lining (Shoe)	18	18	Drum		

Inspection Comments:
 Has this vehicle been road tested? **No**
Inspector: TOOR, SURJIT SINGH
Road Test Date:
Signature:
Road Tester:

This inspection report was submitted to CVSE on 2025-Dec-02 02:16 PM PST
 The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.