

Commercial Vehicle Inspection Report

Decal Number: PY09695
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21496655

Inspection Result:

PASS

FACILITY:	WEST COAST REDUCTION LTD. / P0899	INSP. TYPE:	Complete	INSP. START:	2025-Sep-15 06:00 AM PDT
INSPECTOR:	Smith, James Donald / 105010	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Sep-15 06:45 AM PDT
WORK ORDER #:	341825	INSP. REASON:	Annual		

VEHICLE JUR:	British Columbia	REGI:	03882737	VIN:	2FZHAZDE67AY30316
PLATE #:	RE0687	UNIT/FLEET#:	125	OWNER/LESSEE NAME:	West Coast Reduction Ltd, West Coast Reduction Ltd
PERMITTED GVW(kg):	50000	BODY STYLE:	Dump Truck	ADDRESS:	1292 Venables St, 1292 Venables St
VEHICLE YEAR:	2007	ODOMETER:	702444 KM		Vancouver, British Columbia
MAKE:	STERLING	HUB ODOMETER:			V6A4B4, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Repaired (same day)	#2 D/S SLACK ADJUSTER NOT HOLDING ADJUSTMENT
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	D/S WINDOW CRANK HANDLE DAMAGED AND REGULATOR SCREW MISSING. PASS SIDE REAR FENDER BOLT PULLED THROUGH.
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Repaired (same day)	FIRST AID KIT MISSING

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	42	42	18			18	✓
2	Clamp	30L	Automatic	42	42	18	18	18	18	
3	Clamp	30L	Automatic	42	42	9	9	12	12	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	75	75	Lining (Shoe)	16	16	Drum		
2	60	60	Lining (Shoe)	15	15	Drum		
3	42	42	Lining (Shoe)	15	15	Drum		

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** _____ **Road Tester:** _____

Inspector: Smith, James Donald **Signature:** _____

This Inspection Report was submitted to CVSE on 2025-Sep-15 06:45 AMPDT
 The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

