

Commercial Vehicle Inspection Report

BRITISH COLUMBIA



Decal Number: GJ41745
Decal Expiry Date: 2026-May-31
Inspection Number: 21333589

210-13
Inspection Result
PASS

FACILITY: DUN RITE TRUCK AND TRAILER
INSPECTOR: ADAMS, TREY JUSTIN / 114796
WORK ORDER #: 2377
INSURANCE: REP / S15260
INSURANCE CLASS: INSURANCE REASON: Annual
INSURANCE TYPE: Complete
INSURANCE START: 2025-Apr-21 07:00 AM PDT
INSURANCE COMPLETE: 2025-May-01 08:10 AM PDT

VEHICLE JUR: British Columbia
PLATE #: 16974K
UNLICENSED GVW(kg): 99999
VEHICLE YEAR: 2014
MAKE: RADA
MODEL: RADA
VEHICLE TYPE: Air
FUEL TYPE: FUEL TYPE:
HUB ODOMETER: 10996197
ODOMETER: A229
BODY STYLE: Flat Deck Trailer
UNIT/LEET#: 289CS433ED144360
OWNER/LESSEE NAME: ESSENTIAL TRANSPORT INC.
ADDRESS: 6-1718 BYLAND RD
West Kelowna, British Columbia
V1Z1A9, Canada

Vehicle Identification (VIN)

Section 1 - Power Train
Not Applicable
Section 2 - Suspension
Repaired (same day)
Section 3 - Brake System
Not Applicable
Section 3A - Air Brakes
Repaired (same day)
Section 3H - Hydraulic Brakes
Not Applicable
Section 4 - Steering
Not Applicable
Section 5 - Instruments and Auxiliary Equipment
Not Applicable
Section 6 - Lamps
Passed
Section 7 - Electrical System
Passed

Vehicle Identification (VIN)

Section 8 - Frame and Body
Repaired (same day)
Section 9A - Tires
Passed with Caution
Section 9B - Wheels
Repaired (same day)
Section 10 - Coupling Devices
Repaired (same day)
Section 11 - Other Vehicle Components
Not Applicable

Vehicle Identification (VIN)

Brake Chamber App. Size and Push Rod Stroke (mm)
1 30 Automatic 32
2 30 Automatic 35
3 30 Automatic 32
Brake Lining/Pad (mm)
Left 20 8
Right 10 10
Lining (Shoe) 30 115
Lining (Shoe) 120 30
Lining (Shoe) 100 105
Comment: BRAKES HAVE BEEN REPAIRED

Vehicle Identification (VIN)

Brake Camshaft Rotation (degrees)
Left 30
Right 115
Lining/Pad 20 8
Lining (Shoe) 30 115
Lining (Shoe) 120 30
Lining (Shoe) 100 105
Comment: BRAKES HAVE BEEN REPAIRED

Vehicle Identification (VIN)

Brake Lining/Pad (mm)
Left 20 8
Right 10 10
Lining (Shoe) 30 115
Lining (Shoe) 120 30
Lining (Shoe) 100 105
Comment: BRAKES HAVE BEEN REPAIRED

Vehicle Identification (VIN)

Brake Lining/Pad (mm)
Left 20 8
Right 10 10
Lining (Shoe) 30 115
Lining (Shoe) 120 30
Lining (Shoe) 100 105
Comment: BRAKES HAVE BEEN REPAIRED

Vehicle Identification (VIN)

Brake Lining/Pad (mm)
Left 20 8
Right 10 10
Lining (Shoe) 30 115
Lining (Shoe) 120 30
Lining (Shoe) 100 105
Comment: BRAKES HAVE BEEN REPAIRED

Vehicle Identification (VIN)

Brake Lining/Pad (mm)
Left 20 8
Right 10 10
Lining (Shoe) 30 115
Lining (Shoe) 120 30
Lining (Shoe) 100 105
Comment: BRAKES HAVE BEEN REPAIRED

Vehicle Identification (VIN)

Brake Lining/Pad (mm)
Left 20 8
Right 10 10
Lining (Shoe) 30 115
Lining (Shoe) 120 30
Lining (Shoe) 100 105
Comment: BRAKES HAVE BEEN REPAIRED

Vehicle Identification (VIN)

Brake Lining/Pad (mm)
Left 20 8
Right 10 10
Lining (Shoe) 30 115
Lining (Shoe) 120 30
Lining (Shoe) 100 105
Comment: BRAKES HAVE BEEN REPAIRED