

B264 210-3

# Commercial Vehicle Inspection Report

Decal Number: GK36974  
 Decal Expiry Date: 2026-Dec-31  
 Inspection Number: 21591361

Inspection Result:  
**PASS**

**FACILITY:** AWA MOBILE TRUCK AND TRAILER / S17104  
**INSPECTOR:** ALDIGHIERI DARIO / 300478  
**WORK ORDER #:**

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Annual

**INSP. START:** 2025-Dec-03 12:17 PM PST  
**INSP. COMPLETE:** 2025-Dec-03 02:17 PM PST

**VEHICLE JUR:** British Columbia  
**PLATE #:** R2186J

**REG:** 13601372  
**UNIT/FLEET#:**

**VIN:** 20EMBF920M2039306  
**OWNER/LESSEE NAME:** MERCEDES-BENZ FINANCIAL DIV OF DARTLER TRUCK (U.S.R.) ESSENTIAL TRANSPORT INC

**LICENCED GVW(kg): 0**  
**VEHICLE YEAR:** 2021  
**MAKE:** DODGER  
**MODEL:**

**BODY STYLE:** Flat Deck Trailer  
**ADDRESS:** 6-1718 BYI AVE RD  
 West Kelowna, British Columbia  
 V2Y1A9, Canada

**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**

**Vehicle Identification (VIN)** Passed  
**Section 1 - Power Train** Not Applicable  
**Section 2 - Suspension** Passed  
**Section 3 - Brake System** Passed  
**Section 3A - Air Brakes** Passed  
**Section 3H - Hydraulic Brakes** Not Applicable  
**Section 4 - Steering** Not Applicable  
**Section 5 - Instruments and Auxiliary Equipment** Passed  
**Section 6 - Lamps** Passed  
**Section 7 - Electrical System** Passed  
**Section 8 - Frame and Body** Passed  
**Section 8A - Tires** Passed  
**Section 9B - Wheels** Repaired (same day) ADJUSTED #2 R WHEEL BEARINGS  
**Section 10 - Coupling Devices** Passed  
**Section 11 - Other Vehicle Components** Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	36	36	10	10	7	8	
2	Clamp	30	Automatic	36	36	11	11	11	11	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	33	30	Lining (Shoes)	19	19	Drum	419.25	419.23
2	31	31	Lining (Shoes)	19	19	Drum	419.22	419.22

Comment:

**Inspection Comments:**

Has this Vehicle been road tested?  No **Road Test Date:** **Road Tester:**

**Inspector:** ALDIGHIERI DARIO **Signature:** 

The inspection report is valid only if it is signed by the inspector and the inspector is present at the time of the inspection. The inspector is responsible for the accuracy of the information provided in this report.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION**

Inspection reports are valid only if they are signed by the inspector and the inspector is present at the time of the inspection. The inspector is responsible for the accuracy of the information provided in this report. The information provided in this report is for informational purposes only and does not constitute a warranty or guarantee of any kind. The information provided in this report is subject to change without notice. The information provided in this report is not to be used for any other purpose. The information provided in this report is not to be used for any other purpose. The information provided in this report is not to be used for any other purpose.