

Commercial Vehicle **Inspection Report**

Decal Number: Decal Expiry Date: Inspection Number:

GJ49849 2026-Jul-31 21434664

FACILITY: ROLLS FLEET MAINTENANCE INSP. TYPE: Complete INSP. START 2025-Jul-22 09:30 AM PDT LTD. / S14910 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW INSP. COMPLETE: 2025-Jul-22 12:00 PM PDT INSPECTOR-Cavanagh, Daryl Jay / 113557 5501 kg or more **WORK ORDER #:** INSP. REASON: Annua! VEHICLE JUR: British Columbia REGI: 10439271 1XPWD49X4DD179940 VIN: PLATE #: G81129 UNIT/FLEET#: OWNER/LESSEE NAME: VANDERKOOI RICHARD JAMES. VANDERKOOI LICENCED GVW(kg): 63500 BODY STYLE: Truck Tractor ADDRESS: 9076 GIBSON RD **VEHICLE YEAR:** 2013 ODOMETER: 1143575 KM Chilliwack, British Columbia MAKE: PETERBILT HUB ODOMETER: V2P6H4, Canada MODEL: BRAKE TYPE: Air **FUEL TYPE:** Diese Vehicle Identification (VIN) Passed Section 1 - Power Train Repaired (same day) ADJ. CLUTCH Section 2 - Suspension FIXED LEVELING VALVE ROD Repaired (same day) Section 3 - Brake System Passed Section 3A - Air Brakes Section 3H - Hydraulic Brakes Not Applicable Section 4 - Steering Passed Section 5 - Instruments and Auxiliary Passed Equipment Section 6 - Lamps Repaired (same day) REPAIRED L/R T/S Section 7 - Electrical System Passed Section 8 - Frame and Body Passed Section 9A - Tires Passed with Caution F/L TIRE TREAD LOW Section 9B - Wheels Passed Section 10 - Coupling Devices Passad Section 11 - Other Vehicle Components

Air Brake Chamber Type, Size and Push Rod Stroke (mm)							
Axles	Type	Sizo	Slack Adj.	L			

re brake dilamber type, olze and restricted offore (min)					iire iread Dept					
Axles	Type	Sizo	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Disc	NA	Not Applicable	0	0 -	3.2			4.8	V
2	Clamp	30L	Automatic	36	37	19.8	15.9	15.9	19.8	
3	Clamp	30L	Automatic	42	36	19.8	19.8	19.8	19.8	
Comment:						Comment: CAU	TIONED FRONTS	5		

Air Brake Camshaft Rotation (degrees)		Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	0	0	Pad	20	20	Rotor	45.02	45.03
2	31	28	Lining (Shoe)	21	21	Drum	0.00	0.00
3	40	43	Lining (Shoe)	20	20	Drum	0.00	0.00
Comment:			Comment:			Comment: DNR		

Inspection Comments:

Has this Vehicle been road tested? Inspector: Cavanagh, Daryl Jay

Road Test Date: No Signature:

Road Tester:

This inspection Report was submitted to CVSE on 2025-Jul-22 03:39 PM PDT

The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

Not Applicable