



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

| | | | |
|---------------------------------------|--------------------|------------------------------|--------------|
| Vehicle Type: | Trailer | Seating Capacity: | |
| GVW: | kg | Brake Type: | Air |
| Owner Name: | MFP Resources corp | | |
| Address: | 5920 76 ave nw | | |
| City: | edmonton | Province: | AB |
| Postal Code: | T6B 0A6 | | |
| Telephone Number: | (780) 465-9668 | | |
| Vehicle Identification Number: | 1BN2T39369B010136 | | |
| Make: | Beall | Model: | B-Train Lead |
| Year: | 2009 | Unit Number: | 317 |
| Odometer: | KM | Licence Plate Number: | |
| | | Province: | AB |

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

| | |
|---|---------------------------|
| Inspection Facility Name: | Facility Number: |
| A.R.S. Trucking & Welding Limited | 14481 |
| Inspection Technician Name: | Technician Number: |
| Jason Goller | 05207 |
| Inspection Technician Signature: | |
| Inspection Date: | 2025/08/08 |