



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY00317
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21252570

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS /
N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN /
106407
INSPECTION TYPE: Complete
INSPECTION CLASS: Class 3 - Trailer and Semi-Trailer
INSPECTION REASON: Annual
INSPECTION START: 2025-Feb-26 09:30 AM MST
INSPECTION COMPLETE: 2025-Feb-26 10:30 AM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: 84293K
LICENCED GVM(kg): 0
VEHICLE YEAR: 2014
MAKE: LODE KING
MODEL:
REG: 14579436
UNIT/FLEET: G102
BODY STYLE: Bulk Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2LDMG4534EF057146
OWNER/LESSEE NAME: FORT ST JOHN WATER INC
ADDRESS: 11697 MACLEAN RD
Fort St John, British Columbia
V1J8B3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) CAM BUSHINGS R 2 J
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axis	Type	Size	Stack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	36	35	10	9	11	11	
2	Clamp	30	Automatic	36	34	9	8	10	10	
3	Clamp	30	Automatic	34	36	6	7	8	7	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axis	Left	Right	Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
			Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	72	69	Lining (Shoe)	14	15	Drum		
2	73	22	Lining (Shoe)	14	20	Drum		
3	72	21	Lining (Shoe)	14	21	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? ☒ Yes
Inspector: CHRISTIANSON, LESLIE RYAN
Read Test Date:
Signature:

Read Tester:

This Inspection Report was submitted to CVSE on 2025 Feb-26 10:44 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing the vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code 10.9 regulating carriers, authorized inspectors and designated inspection facilities. If you have any questions about the collection of this information, you may contact the Sr. Manager, NSICVP at the Commercial Vehicle Safety Program.

CVSE0014

2025/02/26 10:44:28 AM MST