

SERVICE SUMMARY HISTORY – Cat Roller CS433E – 8Ton – HX182

Date	Job #	Hrs.	Service Description
04/04/06	-	250	250hrs. service
08/02/07	-	500	500hrs. service
27/08/07	-	750	750hrs. service
18/12/07	-	1,000	1,000hrs. service
21/04/09	-	1,250	250 hr service
29/04/09	-	1,258	Hr. meter replaced
12/11/09	-	301	250hrs. service
06/01/10	-	450	500hrs. service
12/08/10	-	846	750hrs. service
15/10/10	-	950	1,000hrs. service
12/05/11	-	1,258	250hrs. service
11/07/11	-	1,515	500hrs. service
19/09/11	-	1,760	750hrs. service
06/03/12	-	1,926	1,000hrs. service
20/05/13	655	2,205	250hrs. service
10/07/13	778	2,236	Changed oil filter, replaced outer air filter, old one send for wash
05/01/14	1263	2,335	Washed, inspection, running checks, fixed defects
03/02/14	1329	2,363	Replaced 2 batteries
11/02/14	1200	2,365	Replaced injector pump & topped up coolant
10/05/14	1455	2,417	Replaced hydraulic filter
21/05/14	-	2,431	Repaired rheostat (Hastings Deering)
29/05/14	1427	2,475	500hrs. service
16/06/14	1510	-	Replaced 2-way handpiece
25/09/14	-	2,528	Replaced vibration frequency controller (Hastings Deering)
19/12/17		2,777	750hr service
21/08/18			Replace LH & RH Steering ram seals
13/09/18		2946	1000hr Service, repaired lights, rear indicators, twoway



SERVICE SUMMARY HISTORY – Cat Roller CS433E – 8Ton – HX182

26/02/2019		3028	250hr service
7/8/19		3251	250hr service
13/07/2020		3529	Replaced two batteries
15/07/2020		3523	Replace alternator
14/07/2020		3538	500hr Service
23/09/2020		3569	Fit compactor shells
10/03/2021		3676	3500hr Service
27/05/2021		3706	3750hr Service
17/07/2022		4073	4000hr service
31/08/2022			Replaced Electric fuel pump – information to be updated 07-09-2022 CW
Feb2023		4250	Carried out 250Hour Service
27/07/2023		4556	Carried out 4500Hr Service
16/08/2023		4563	Replaced Bonnet Latch Replaced Engine Mounts Resealed Fuel Pump
06/03/2024		4610	Diag faulty ECM Vibe. Hastings replaced Controller and vibe system was repaired. Copy of hastings invoice in Z Drive
17/06/24		4743	750 hr service
20/01/26		5058	1000HR Service, Painted