

STONY INSPECTION SERVICES INC.

21-52211 Range Road 275, Spruce Grove, Alberta T7X 3V1
(780)963-6820 admin@stonyinspection.ca

BalinValley Enterprises Ltd
c/o VanGenderen Canada Inc.
10485 Fulton Drive
Acheson, Alberta T7X 6A1

Attention: Reina VanGenderen

25 March 2025



Re: Certification of Tadano AT crane
Model: ATF 110G-5 Serial: 2035157
Year: 2006 Capacity: 130 tons
Unit: VG-23
Stony Inspection Services Job: 57234

Dear Sir/Madame:

An inspection of the structural elements of the above AT crane was completed by Stony Inspection Services, acting under our direction (Stony Inspection Services Job 57234, dated 25 March 2025, copy attached). The inspection was structural only; no load tests or operational tests were performed. In addition to this structural inspection, the owner and operator are responsible for complying with original equipment manufacturer specifications, OH&S regulations, and the applicable CSA Z-150 and/or ASME B30.5 codes with respect to all inspection, maintenance, and operations of the unit.

Based on this inspection, the above unit is considered structurally fit for continued service.

Yours truly,



G. Layden
59847
2025-03-26

Gaylene D. K. Layden, P.Eng.
Stony Engineering Inc.

STONY INSPECTION

SERVICES INC.

21-52211 Range Road 275 Spruce Grove, AB T7X 3V1
780-963-6820 office@stonyinspection.ca

Balinvalley Enterprises Ltd.
766 Wheeler Road
Edmonton, Alberta T6M 2E6

Attention: Leo Davis

9 March 2024


TEN YEAR BOOM TEAR DOWN AS PER CSA Z150 STANDARD

Re: Certification of Tadano Crane Boom Sections
Model: ATF 110G-5 Serial: 2035157
Year: ---- Capacity: 130 Ton
Unit: VG-23
Stony Inspection Services Job: 51933

Dear Sir/Madame:

Further to the inspection of the structural elements of the above disassembled crane boom by Stony Inspection Services, acting under our direction (Stony Inspections Services Job 51933, dated 9 March 2024, copy attached), the above sections are considered structurally fit for continued service.

Yours truly,



PERMIT TO PRACTICE	
STONY ENGINEERING INC.	
RM SIGNATURE:	<i>[Signature]</i>
RM APEGA ID #	59847
DATE:	2024-03-11
PERMIT NUMBER: P014039	
The Association of Professional Engineers and Geoscientists of Alberta (APEGA)	

Gaylene D. K. Layden, P. Eng.
Stony Engineering Inc.

Association of Professional Engineers & Geoscientists of Saskatchewan		
CERTIFICATE OF AUTHORIZATION		
Stony Engineering Inc.		
Number 39856		
Permission to Consult held by:		
Discipline	Sk Reg No	Signature
	21061	<i>[Signature]</i>

STONY INSPECTION

SERVICES INC.

21-52211 Range Road 275 Spruce Grove, AB T7X 3V1
780-963-6820 office@stonyinspection.ca

Balinalley Enterprises Ltd.
766 Wheeler Road
Edmonton, Alberta T6M 2E6

20 March 2024

FIVE-YEAR LOAD BLOCK TEARDOWN AS PER CSA Z150 STANDARD

Re: Certification of Faun Block
Load Block Model: H4916 Serial: 005089 Capacity: 80 tonne
Stony Inspection Services Job: 52141

Dear Sir:

Further to the inspection of the structural elements of the above disassembled block by Stony Inspection Services, acting under our direction (Stony Inspections Services Job 52141, dated 20 March 2024, copy attached), the above unit is considered structurally fit for continued service.

Yours truly,



59847

EGBC Permit No. 1001808

Gaylene D. K. Layden, P. Eng.
Stony Engineering Inc.

Association of Professional Engineers & Geoscientists of Saskatchewan		
CERTIFICATE OF AUTHORIZATION		
Stony Engineering Inc. Number 39856		
Permission to Consult held by:		
Discipline	Sk. Reg. No.	Signature
	21061	

PERMIT TO PRACTICE STONY ENGINEERING INC.	
RM SIGNATURE	
RM APEGA ID #	59847
DATE	2024-03-20
PERMIT NUMBER: P014039	
The Association of Professional Engineers and Geoscientists of Alberta (APEGA)	