

F24-39
BLUE-MAR

268 Clearview Drive
Red Deer County, AB T4E 0A1
Tel 403-340-2225
Email admin@iconenergyservices.ca



May 22, 2025

TeKh Group Inc.
Box 37
Eckville, AB, T0M 0X0

ENGINEERING CERTIFICATION

Equipment	Side Boom	Job/Report #	DS-0958
Make	Caterpillar	Inspection Date	May 22, 2025
Model	D6C	Inspection Due	May 22, 2026
Serial Number	90B596	Unit#	72-634
Capacity	Refer to OEM Specifications		
Inspector Name (NDT)	Darrell Spence		
Applicable Notes			

Icon Energy Services Ltd's technical staff performed a non-destructive examination of accessible structural load bearing components on the aforementioned equipment in accordance with Icon Energy Services Ltd's procedures, industry standard practices, and/or OEM recommendations as applicable. Upon final inspection of the equipment and any repairs recommended or performed, no unacceptable defects were noted.

Based on the results of our final inspection and assessment, it is our opinion that the aforementioned equipment is safe for use provided routine maintenance is performed according to the original equipment manufacturer's specifications.

This Certification is Valid for 1 Year

Certifying Engineer and Responsible Member
APEGA PERMIT# P11646/ APEGS# 41615/ EGBC# 1002985



Date May 22, 2025

Doc#	Rev.	Doc Name
ENG-0510-00	0	Annual Equipment Certification