

# STONY INSPECTION SERVICES INC.

21-52211 Range Road 275, Spruce Grove, Alberta T7X 3V1  
(780)963-6820 admin@stonyinspection.ca

Jonnys Light Oilfield Hauling Ltd.  
Box 214, 2120 Sparrow Drive  
Nisku, Alberta T9E 8A2

Attention: Michelle Larkin

30 May 2025


Re: Certification of Fassi telescopic/articulating picker  
Model: F24.0B.24 Serial: 3773  
Year: 2006 Capacity: 16667 lbs  
Unit: 54  
Stony Inspection Services Job: 58186

Dear Sir/Madame:

An inspection of the structural elements of the above telescopic/articulating picker was completed by Stony Inspection Services, acting under our direction (Stony Inspection Services Job 58186, dated 30 May 2025, copy attached). The inspection was structural only; no load tests or operational tests were performed. In addition to this structural inspection, the owner and operator are responsible for complying with original equipment manufacturer specifications, OH&S regulations, and the applicable CSA Z-150 and/or ASME B30.5 codes with respect to all inspection, maintenance, and operations of the unit.

Based on this inspection, the above unit is considered structurally fit for continued service.

Yours truly,



59847

<b>PERMIT TO PRACTICE</b>	
<b>STONY ENGINEERING INC.</b>	
PM SIGNATURE	_____
PM APEGA ID #	59847
DATE	2025-06-02
<b>PERMIT NUMBER: P014039</b>	
The Association of Professional Engineers and Geoscientists of Alberta (APPGA)	

Gaylene D. K. Layden, P.Eng.  
Stony Engineering Inc.

Association of Professional Engineers & Geoscientists of Saskatchewan		
CERTIFICATE OF AUTHORIZATION		
Stony Engineering Inc		
Number 39856		
Permission to Consult held by		
Discipline	SK Reg No	Signature
_____	21111	_____