

# STONY INSPECTION SERVICES INC.

21-52211 Range Road 275, Spruce Grove, Alberta T7X 3V1  
(780)963-6820 admin@stonyinspection.ca

Jonny's Light Oilfield Hauling Ltd.  
Box 214, 2120 Sparrow Drive  
Nisku, Alberta T9E 8A2

Attention: Michelle Larkin

30 May 2025



Re: Certification of Manitex telescopic/articulating picker  
Model: 4596T Serial: 190797  
Year: N/A Capacity: 45 tons  
Unit: 89  
Stony Inspection Services Job: 58187

Dear Sir/Madame:


An inspection of the structural elements of the above telescopic/articulating picker was completed by Stony Inspection Services, acting under our direction (Stony Inspection Services Job 58187, dated 30 May 2025, copy attached). The inspection was structural only; no load tests or operational tests were performed. In addition to this structural inspection, the owner and operator are responsible for complying with original equipment manufacturer specifications, OH&S regulations, and the applicable CSA Z-150 and/or ASME B30.5 codes with respect to all inspection, maintenance, and operations of the unit.

Based on this inspection, the above unit is considered structurally fit for continued service.

Yours truly,



59847



Gaylene D. K. Layden, P.Eng.  
Stony Engineering Inc.

