

F47-2  
MAY



**SLICK**  
**INSPECTION LTD.**  
**403-581-9887**  
Medicine Hat, AB

**GSY OILFIELD TECHNOLOGIES INC.**  
226 VISTA CLOSE S.E.  
MEDICINE HAT, AB T1B 0C4  
TEL: 403-866-6888

**SLICK INSPECTION LTD.**  
2038 12th AV, N.W.  
MEDICINE HAT, AB T1C 2A7  
TEL: 403-581-9887

**FILE NO.: GED-26-6426**

**ENGINEERING CERTIFICATION**

**EQUIPMENT:** CRANE TRUCK  
**MAKE:** NATIONAL  
**MODEL:** 1100  
**SERIAL:** 2259  
**OWNER:** BIG J CRANE  
**OWNER UNIT #:** 101  
**CERTIFIED DATE:** April 14, 2026

Based on thorough inspections performed by Slick Inspection Ltd. on April 9, 2026 described in Slick Equipment Inspection Report No. 26-308, I certify that the critical structural, mechanical and control components of the inspected equipment are safe for continued use in accordance with CSA Z150-11 Section 5.3.2.2 which requires an annual inspection, complete inspection if damaged or disassembled, and telescopic boom magnetic particle inspection every five years.

Equipment must be maintained in accordance with manufacturer's recommendations, operated in safe procedure without exceeding rated capacity. This certification is not transferable to new owner. This certification is valid for a maximum period of one year from the inspection date. The unit is to be reinspected if it sustains damage to a structural area and under any approved repairs.

GSY OILFIELD TECHNOLOGIES INC.



APEGA ID: 83361  
April 14, 2026

Xiang Gao, P.ENG.

**PERMIT TO PRACTICE**  
GSY OILFIELD TECHNOLOGIES INC.  
Signature [Signature]  
Date April 14, 2026  
**PERMIT NUMBER: P 10906**  
The Association of Professional Engineers,  
Geologists and Geophysicists of Alberta

APEGA ID: 83361