

268 Clearview Drive
Red Deer County, AB T4E 0A1
Tel: 403-340-2225
Email: admin@iconenergyservices.ca



June 1, 2025

Challand Pipeline Ltd.
PO Box 1807
Rocky Mountain House, AB, T4T 1B4

ENGINEERING CERTIFICATION

Equipment	Side Boom	Job/Report #	DS-0994
Make	Caterpillar	Inspection Date	June 1, 2025
Model	D6D	Inspection Due	June 1, 2026
Serial Number	04X06906	Unit#	126
Capacity	40,000 lbs		
Inspector Name (NDT)	Darrell Spence		
Applicable Notes			

Icon Energy Services Ltd's technical staff performed a non-destructive examination of accessible structural load bearing components on the aforementioned equipment in accordance with Icon Energy Services Ltd's procedures, industry standard practices, and/or OEM recommendations as applicable. Upon final inspection of the equipment and any repairs recommended or performed, no unacceptable defects were noted.

Based on the results of our final inspection and assessment, it is our opinion that the aforementioned equipment is safe for use provided routine maintenance is performed according to the original equipment manufacturer's specifications.

This Certification is Valid for 1 Year

Certifying Engineer and Responsible Member
APEGA PERMIT# P11646/ APEGS# 41615/ EGBC# 1002985



Date June 1, 2025

Doc#	Rev.	Doc Name
ENG-0510-00	0	Annual Equipment Certification