

FY17-22

268 Clearview Drive  
Red Deer County, AB T4E 0A1  
Tel: 403-340-2225  
Email: admin@iconenergyservices.ca



June 1, 2025

Challand Pipeline Ltd.  
PO Box 1807  
Rocky Mountain House, AB, T4T 1B4

## ENGINEERING CERTIFICATION


|                             |                |                        |              |
|-----------------------------|----------------|------------------------|--------------|
| <b>Equipment</b>            | Side Boom      | <b>Job/Report #</b>    | DS-0993      |
| <b>Make</b>                 | Caterpillar    | <b>Inspection Date</b> | June 1, 2025 |
| <b>Model</b>                | D6D            | <b>Inspection Due</b>  | June 1, 2026 |
| <b>Serial Number</b>        | 04X06693       | <b>Unit#</b>           | 161          |
| <b>Capacity</b>             | 40,000 lbs     |                        |              |
| <b>Inspector Name (NDT)</b> | Darrell Spence |                        |              |
| <b>Applicable Notes</b>     |                |                        |              |

Icon Energy Services Ltd's technical staff performed a non-destructive examination of accessible structural load bearing components on the aforementioned equipment in accordance with Icon Energy Services Ltd's procedures, industry standard practices, and/or OEM recommendations as applicable. Upon final inspection of the equipment and any repairs recommended or performed, no unacceptable defects were noted.

Based on the results of our final inspection and assessment, it is our opinion that the aforementioned equipment is safe for use provided routine maintenance is performed according to the original equipment manufacturer's specifications.

This Certification is Valid for 1 Year

Certifying Engineer and Responsible Member  
APEGA PERMIT# P11646/ APEGS# 41615/ EGBC# 1002985



Date June 1, 2025

| Doc#        | Rev. | Doc Name                       |
|-------------|------|--------------------------------|
| ENG-0510-00 | 0    | Annual Equipment Certification |