

FY17-52

268 Clearview Drive
Red Deer County, AB T4E 0A1
Tel: 403-340-2225
Email: admin@iconenergyservices.ca



June 1, 2025

Challand Pipeline Ltd.
PO Box 1807
Rocky Mountain House, AB, T4T 1B4

ANNUAL CERTIFICATION – STRUCTURAL INSPECTION

Equipment	Articulating Crane		
Make	Palfinger	Job/Report #	DS-0996
Model	PK60002	Inspection Date	June 1, 2025
Serial Number	100139836	Inspection Due	June 1, 2026
Capacity	46,296 lbs	Unit#	1321
Inspector Name (NDT)	Darrell Spence		
Applicable Notes			

Icon Energy Services Ltd's technical staff performed visual and non-destructive examination of accessible structural load bearing components on the aforementioned equipment in accordance with Icon Energy Services Ltd's procedures, industry standard practices, and/or OEM recommendations as applicable. Upon final inspection of the equipment and any repairs recommended or performed, no unacceptable defects were noted.

Based on the results of our final inspection and assessment, it is our opinion that the aforementioned equipment is structurally safe for use with regular inspections as per the standards and regulations below as applicable.


Note: BC OHSR Regulations require an additional mechanical and control certification not covered by this certification document.

This Certification is Valid for 1 Year

Applicable Codes (Current Ed)

CSA Z150 – Safety Code on Mobile Cranes
CSA Z150.3 – Safety Code on Articulating Boom Cranes
Occupational Health and Safety Code (Alberta) – Part 6
Occupational Health and Safety Regulation (OHSR - British Columbia) – Section 14
Occupational Health and Safety Regulation (OHSR - Saskatchewan) – Section XIII

Certifying Engineer and Responsible Member
APEGA PERMIT# P11646/ APEGS# 41615/ EGBC# 1002985



Date June 1, 2025

Doc#	Rev.	Doc Name
ENG-0511-00	1	Annual Mobile Crane Certification