

FY17-51

268 Clearview Drive
 Red Deer County, AB T4E 0A1
 Tel: 403-340-2225
 Email: admin@iconenergyservices.ca



May 28, 2025

Challand Pipeline Ltd.
 PO Box 1807
 Rocky Mountain House, AB, T4T 1B4

ANNUAL CERTIFICATION – STRUCTURAL INSPECTION

Equipment	Telescopic Crane		
Make	Maxilift	Job/Report #	DH-4021
Model	4400WE	Inspection Date	May 28, 2025
Serial Number	24990	Inspection Due	May 28, 2026
Capacity	4,400 lbs	Unit#	1636
Inspector Name (NDT)	Devon Hoffensetz		
Applicable Notes			

Icon Energy Services Ltd's technical staff performed visual and non-destructive examination of accessible structural load bearing components on the aforementioned equipment in accordance with Icon Energy Services Ltd's procedures, industry standard practices, and/or OEM recommendations as applicable. Upon final inspection of the equipment and any repairs recommended or performed, no unacceptable defects were noted.

Based on the results of our final inspection and assessment, it is our opinion that the aforementioned equipment is structurally safe for use with regular inspections as per the standards and regulations below as applicable.

Note: BC OHSR Regulations require an additional mechanical and control certification not covered by this certification document.

This Certification is Valid for 1 Year

Applicable Codes (Current Ed)

CSA Z150 – Safety Code on Mobile Cranes

CSA Z150.3 – Safety Code on Articulating Boom Cranes

Occupational Health and Safety Code (Alberta) – Part 6

Occupational Health and Safety Regulation (OHSR - British Columbia) – Section 14

Occupational Health and Safety Regulation (OHSR - Saskatchewan) – Section XIII

Certifying Engineer and Responsible Member
 APEGA PERMIT# P11646/ APEGS# 41615/ EGBC# 1002985



Date May 28, 2025

Doc#	Rev.	Doc Name
ENG-0511-00	1	Annual Mobile Crane Certification