

268 Clearview Drive
Red Deer County, AB T4E 0A1
Tel: 403-340-2225
Email: admin@iconenergyservices.ca



May 28, 2025

Challand Pipeline Ltd.
PO Box 1807
Rocky Mountain House, AB, T4T 1B4

ANNUAL CERTIFICATION – STRUCTURAL INSPECTION

Equipment	Articulating Crane	Job/Report #	DH-4024
Make	Hiab	Inspection Date	May 28, 2025
Model	X-CLX 078 BS-3	Inspection Due	May 28, 2026
Serial Number	BL078CX00146	Unit#	2092
Capacity	3,350 kg		
Inspector Name (NDT)	Devon Hoffensetz		
Applicable Notes			

Icon Energy Services Ltd's technical staff performed visual and non-destructive examination of accessible structural load bearing components on the aforementioned equipment in accordance with Icon Energy Services Ltd's procedures, industry standard practices, and/or OEM recommendations as applicable. Upon final inspection of the equipment and any repairs recommended or performed, no unacceptable defects were noted.

Based on the results of our final inspection and assessment, it is our opinion that the aforementioned equipment is structurally safe for use with regular inspections as per the standards and regulations below as applicable.

Note: BC OHSR Regulations require an additional mechanical and control certification not covered by this certification document.

This Certification is Valid for 1 Year

Applicable Codes (Current Ed)

CSA Z150 – Safety Code on Mobile Cranes

CSA Z150.3 – Safety Code on Articulating Boom Cranes

Occupational Health and Safety Code (Alberta) – Part 6

Occupational Health and Safety Regulation (OHSR - British Columbia) – Section 14

Occupational Health and Safety Regulation (OHSR - Saskatchewan) – Section XIII

Certifying Engineer and Responsible Member
APEGA PERMIT# P11646/ APEGS# 41615/ EGBC# 1002985



Date May 28, 2025

Doc#	Rev.	Doc Name
ENG-0511-00	1	Annual Mobile Crane Certification