

STONY INSPECTION SERVICES INC.

21-52211 Range Road 275, Spruce Grove, Alberta T7X 3V1
(780)963-6820 admin@stonyinspection.ca

Z30-2
Aug

Just Call Johnny Motors Ltd.
11108-83 Avenue
Fort Saskatchewan, Alberta T8L 0G5

Attention: John Golubic

29 July 2026


Re: Certification of HIAB telescopic/articulating picker
Model: 122 B-2 CLX Serial: 12204353
Year: 2005 Capacity: 3800 kgs
Unit: ----
Stony Inspection Services Job: 64186

Dear Sir/Madame:

An inspection of the structural elements of the above telescopic/articulating picker was completed by Stony Inspection Services, acting under our direction (Stony Inspection Services Job 64186, dated 29 July 2026, copy attached). The inspection was structural only; no load tests or operational tests were performed. In addition to this structural inspection, the owner and operator are responsible for complying with original equipment manufacturer specifications, OH&S regulations, and the applicable CSA Z-150 and/or ASME B30.5 codes with respect to all inspection, maintenance, and operations of the unit.

Based on this inspection, the above unit is considered structurally fit for continued service.

Yours truly,



Gaylene D. K. Layden, P.Eng.
Stony Engineering Inc.

59847

Digitally signed; copy if printed.

Association of Professional Engineers & Geoscientists of Saskatchewan		
CERTIFICATE OF AUTHORIZATION Stony Engineering Inc. Number 39856		
Permission to Consult held by:		
Discipline	Sk. Reg. No.	Signature
	21061	(signature)

STONY INSPECTION SERVICES INC.

21-52211 Range Road 275
Spruce Grove, Alberta T7X 3V1
(780)963-6820 admin@stonyinspection.ca

Company Name: Just Call Johnny Motors Ltd.

Address: 11108-83 Avenue

City/Province: Fort Saskatchewan, Alberta

T8L 0G5

ContactName John Golubic

Contact Phone: (604) 845-4822

Date: 29-Jul-26

Job Number: 64186

P.O.#:

Equip Type: MOBILE CRANE

Equip Sub Type: telescopic/articulating picker

Equip Make: HIAB

Serial Number: 12204353

N/A:

Surface Condition: Fair

Equip Model: 122 B-2 CLX

Unit#1:

Unit#2:

Capacity: 3800 kgs

Year: 2005

The following was noted at the time of inspection:

ACCEPTABLE:

No relevant indications were noted.

Repairs Required: N

Sticker On Unit: Y

Certification Required: Y

Province: AB, SK

Technician: Rachel Clarke

STONY INSPECTION SERVICES INC.

21-52211 Range Road 275
Spruce Grove, Alberta T7X 3V1
(780)963-6820 admin@stonyinspection.ca

Company Name: Just Call Johnny Motors Ltd.

Address: 11108-83 Avenue

City/Province: Fort Saskatchewan, Alberta

ContactName John Golubic

T8L 0G5

Contact Phone: (604) 845-4822

Date: 29-Jul-26

Job Number: 64186

P.O.#:

MOBILE CRANE-telescopic/articulating picker	VIS	MPI	LPI	N/A	Notes
Platform & rails	☐	☒	☐	☐	
Main boom sections	☐	☒	☐	☐	
Front out riggers	☐	☐	☐	☒	
Rear out riggers	☐	☒	☐	☐	
Pedestal	☐	☒	☐	☐	
Turret and boom mount	☐	☒	☐	☐	
Frame mounts	☐	☒	☐	☐	
Frame cross members	☐	☒	☐	☐	
Winch mounts	☐	☒	☐	☐	
Jib sections	☐	☐	☐	☒	
Cylinder mounts	☐	☒	☐	☐	
Load Block / Headache Ball	☐	☒	☐	☐	
Grapple tongs	☐	☐	☐	☒	
Load chart	☒	☐	☐	☐	
Log book	☒	☐	☐	☐	
Boom camber or twist	☒	☐	☐	☐	
Boom angle indicator	☒	☐	☐	☐	
Anti two block device	☒	☐	☐	☐	
Main hoist line & whip line Spooled	☒	☐	☐	☐	
Forks	☐	☐	☐	☒	