

W19-314
NOV



11579 Chevron Frontage Road
Fort St. John, BC

Tel: 250-793-1009
Fax: 250-785-9383

Tank Cleaning Confirmation

Date: Oct 7/26

Unit #: 902

Trailer #: 903

Previous BOL#: _____

Compartment

Residue Last Contained

<u>Sulphur</u>

Product Used to Flush:	<u>Hot water</u>
Drain Water/Residue	<u>Pass</u> Fail
Piping is Drained	<u>Pass</u> Fail
Tank is Clean	<u>Pass</u> Fail

Operator
Signature [Signature]

Print Name Rody Pearson

Inspected by:
Signature _____

Print Name & Title _____