



TANK INSPECTION

Our Mailing Address:

115, 55202 - SH 825

Sturgeon County, AB T8L 5C1

Phone 780-977-0523 | Fax 780-977-0034

BILL OF LADING / RECYCLE DOCKET

(circle one)

No 01350

CONSIGNOR

c/o ProNorth.

Name: Ritchie Brothers

Address: 1500 sparrow Dr

City & Province: Nisku, AB

Postal Code: T80-965-9929

CONSIGNEE

Name: Recycle West

Address: 6603 - 30 Street

City & Province: Edmonton AB

Postal Code: ABR 10137

Date Received: _____

FLHA: _____

Date: June 10, 2026 (DD/MM/YY)

CARRIER Truck
PRONORTH ENVIRONMENTAL SERVICES
#4,115 STURGEON CR.
STURGEON COUNTY, AB T8L 5C1

Unit Number: 23

VIN # 2AEFSW K H 8 A E 000 102

UNIT # R65/3 2010 Advance Tri/A vacuum tanker.

PO # 110486767

INSPECT EMPTY RESIDUE TO BE CLEANED

PURGE TANK CLEANING & PURGE

WASHING

DESCRIPTION OF WORK: *Fluid in tank and Rear hose leaking on ground.
Cleaned hose that was leaking on ground.
Steamed trailer until we got water @ Rear Valve.*

DG	SHIPPING NAME	CLASS	UN	PACKING GROUP	MASS OR VOLUME		NO. OF PKGS.
					EST	UNIT	
✓	Crude to wash water.	TI	1267	03	3500	kg.	01
TOTAL GROSS MASS						KG	

Special Instructions (Comments, Emergency Plan)
*Truck not hooked up, no way to function any controls.
Could still be solids in tank*

IN CASE OF EMERGENCY CALL PRONORTH'S 24-HR NUMBER 780-977-0523

Placards Required (Type / Number):
Notes:
EUB Manifest: Federal Waste Manifest:

CONSIGNOR Print Name: <u>As per Sarah</u> Signature: <u>780-955-4609.</u>	CONSIGNEE Print Name: _____ Signature: _____	CARRIER Print Name: <u>Gary Moffet</u> Signature: _____
--	---	--