



Dynamic Industrial Solutions
 1791 30th St SW
 Medicine Hat, AB T1B 3N5
 Tel. 403-527-7272 Fax 403-529-6526
 payment@dynamicis.ca


Roy-9 Jun
 WORK ORDER

TANK-7729

Tank Inspection

Ordered By: NORM	Date: 7-May-26
Customer: Rafter 9 Oilfield Services Inc.	Facility:
Location: UNIT T-2	Job Number:
Description Of Work	
WORK REQUIRED STEAM UNIT AND SUPPLY STEAM REPORT	
WORK COMPLETED ✓ UNIT INSPECTED AND STEAM REPORT COMPILED ✓	

Steamed out !!

Technician Signature: 	Totals:	Labour	\$0.00
		Parts	\$0.00
Customer Name: Rafter 9		Travel	\$0.00
		Rentals	\$0.00
Customer Approved: <input checked="" type="checkbox"/> Order Accepted		Miscellaneous	\$0.00
		Subsistence	\$0.00
Inspection:	Date:	Sub Total:	\$0.00
Remit Payment To: Dynamic Industrial Solutions 1791 30th St SW Medicine Hat, AB T1B 3N5 Tel. 403-527-7272 Fax 403-529-6526 payment@dynamicis.ca BN:857198857 RT 0001			Work Order Total: \$0.00

