


M25-6  
JW




As Found Report		Location
Submitted By	<u>Zachariah Zoschke</u>	
Surrogate	<u>Zachariah Zoschke</u>	
Started On	May 21 2026, 9:11am	
Submitted On	May 21 2026, 2:40pm (5 hours)	
Weather	63°, cloudy	
Version	V1 (latest)	
Updated	May 21 2026, 2:40pm	
Report No.	81848666	


As Found Report	
Job Number:	26068
Client:	Keyera
LSD:	Keyera fort Saskatchewan
Equipment ID:	Tank numbers #4018, #4004, #4034, #4005
Date:	May 21st 2026 09:32
As Found Condition of equipment:	Arrived at R/T rentals to clean 400 bbl tanks from keyera fort Saskatchewan site. Open man ways on all 4 tanks, inspect debris left in tanks from site. Small amount of debris in all 3 slop tanks, fresh water tank was clean but still washed, degreased & continued on. Scrubbed tanks with degreaser & let it soak. Utilized high pressure from wash pump and hot water to wash tanks.
Photos of Equipment	None
	<p>NOTE:</p> <p>Debris from slop tanks left standing in tank, used pressure washer pump, chemical former/chemical canister to apply and wash debris on floor, walls and roof of 400 bbl tanks. Lemonlite, envirosol and PinkRoc in tanks to degrease and de-gas. Wash chemical and debris with hot water and higher pressure.</p>




4018 before clean




#4004 before clean




#4005 before clean




#4034 before clean




#4004 after cleaning



#4018 after clean



#4034 after clean



#4005 after clean

Generated Thursday, May 21st 2026, 4:15pm CDT

powered by  KPA