

H06-3
JUG



ADVANCE TANK CENTRES


Date: JULY 7/26
 Customer: OCULUS TRANSPORT Job #: PV12-14
 Work Order No: ATC6815370001 Serial No: 41707A
 Employee Name: B. ROWLEY Clock #: 2401

On this date, Advance Tank Centres rendered this tank safe.

It is important to recognize that:

- In order to do so, it may have been necessary to steam or otherwise introduce water in the tank, it's pipeline and other accessories.
- There is a danger of damage to the tank or its equipment through freezing. It is your responsibility to take precautions to avoid such damage. Advance specifically disclaims any liability for damage of this sort.
- As part of the process, pipelines may be left unconnected. Manholes and other devices may also be open and these must be identified and dealt with. This is your responsibility.
- Prior to being placed back into service all piping connections, valves etc. should be checked and the system should be purged to remove moisture or other contaminants introduced during the steaming or repair operations.
- While this tank was rendered safe on this date is no assurance that it will remain so. It is very important to recognize that this tank may re-gas or otherwise become dangerous at any time and without additional hazardous material being added to the tank. This tank must be retested for safety before any operations are carried out on it or before and after it is moved into a hazardous environment. This would include a shop. This retesting is responsibility; Advance specialy disclaims any liability for and future dealings with this tank once it has left our control.

Read and understood this 9 day of July, 2026.

Signed: 
Peter Hayes
 (Print Name)

On behalf of Oculus Transport Ltd.