

<b>FACILITY:</b>	NORTHERN B.C. TRUCKERS' / N5398	<b>INSP. TYPE:</b>	Complete	<b>INSP. START:</b>	2026-May-07 11:22 AM MST
<b>INSPECTOR:</b>	CHRISTIANSON, LESLIE RYAN / 106407	<b>INSP. CLASS:</b>	Class 3 - Trailer and Semi-Trailer	<b>INSP. COMPLETE:</b>	2026-May-07 12:20 PM MST
<b>WORK ORDER #:</b>		<b>INSP. REASON:</b>	Semi-annual		

<b>VEHICLE JUR:</b>	British Columbia	<b>REGI:</b>	02988499	<b>VIN:</b>	2D9DS5C32YL017494
<b>PLATE #:</b>	66940C	<b>UNIT/FLEET#:</b>	233	<b>OWNER/LESSEE NAME:</b>	J Bueckert logging Ltd , .
<b>LICENCED GVW(kg):</b>	999999	<b>BODY STYLE:</b>	Dump Trailer	<b>ADDRESS:</b>	11706 Maclean rd
<b>VEHICLE YEAR:</b>	2000	<b>ODOMETER:</b>			Fort St John, British Columbia
<b>MAKE:</b>	DECAP	<b>HUB ODOMETER:</b>			V1j8b3, Canada
<b>MODEL:</b>		<b>BRAKE TYPE:</b>	Air		
		<b>FUEL TYPE:</b>			

<b>Vehicle Identification (VIN)</b>	Passed
<b>Section 1 - Power Train</b>	Not Applicable
<b>Section 2 - Suspension</b>	<b>Repaired (same day)</b> R1 r3 spring and equiliser
<b>Section 3 - Brake System</b>	Passed
<b>Section 3A - Air Brakes</b>	<b>Repaired (same day)</b> R3 pot
<b>Section 3H - Hydraulic Brakes</b>	Not Applicable
<b>Section 4 - Steering</b>	Not Applicable
<b>Section 5 - Instruments and Auxiliary Equipment</b>	Not Applicable
<b>Section 6 - Lamps</b>	Passed
<b>Section 7 - Electrical System</b>	Passed
<b>Section 8 - Frame and Body</b>	Passed
<b>Section 9A - Tires</b>	Passed
<b>Section 9B - Wheels</b>	Passed
<b>Section 10 - Coupling Devices</b>	Passed
<b>Section 11 - Other Vehicle Components</b>	Not Applicable

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	36	37
2	Clamp	30	Automatic	34	35
3	Clamp	30	Automatic	36	33
<b>Comment:</b>					

Outer L	Inner L	Inner R	Outer R	Steering
10	10	10	11	
15	14	20	21	
16	16	9	10	
<b>Comment:</b>				


Axles	Left	Right
1	62	69
2	90	72
3	62	69
<b>Comment:</b>		

Lining/Pad	Left	Right
Lining (Shoe)	16	15
Lining (Shoe)	12	14
Lining (Shoe)	12	12
<b>Comment:</b>		

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		
<b>Comment:</b> Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

**Inspection Comments:**

Has this Vehicle been road tested?  No  Yes      **Road Test Date:** \_\_\_\_\_      **Road Tester:** \_\_\_\_\_

**Inspector:** CHRISTIANSON, LESLIE RYAN      **Signature:** 

This Inspection Report was submitted to CVSE on 2026-May-07 01:01 PM MST  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/7/2026 1:01:33 PM MST