04131287

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL VOID WITHOUT SEAL
Manitoba
C114036

Date Inspection Started: DAY 10 MO. 06 YR. 26
Date Inspection Completed: DAY 10 MO. 06 YR. 26
Inspection Expiry Date: DAY 30 MO. 06 YR. 27

Station Number: A51951 Station Name: KMMJ LTD City: Vista
Mechanic Number: M012018 Mechanic Signature: [signature] Station Phone Number: 2048573838

Vehicle Owner: 5214165 Manitoba Ltd
Address: Box 441 City: Souris Province: MB Postal Code: R0K2C0 Phone:

[X] Pass/Safe Vehicle
[ ] Fail/Unsafe Vehicle
[ ] Fail/Hazardous

Licence Number: CKJ9167 Prov.: MB NSC #: 0997627 Odometer Reading: 585156 Odom. Type: [X] km [ ] mi
Vehicle Identification Number: 1XKWD149X2PR75259 Make: KW Model: W900 Year: 23 Unit #: 16
[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR 24158 KGS ___X___Truck Tractor ____Trailer ____Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any) Rear III) marker light port, rear
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining IN L	Lining IN R	Drum/Rotor IN L	Drum/Rotor IN R	Stroke IN L	Stroke IN R
1	.70	.70	15.06	15.06	1 1/2	1 1/2
2	.68	.68	16.55	16.55	1 1/2	1 1/2
3	.65	.70	16.56	16.54	1 1/2	1 1/2
4						
5						
	Final Measurement					

Axle	Tread Depth Initial 32nds L		Tread Depth Initial 32nds R		Tread Depth Corrected L		Tread Depth Corrected R		Air Pressure Initial PSI L		Air Pressure Initial PSI R		Air Pressure Corrected L		Air Pressure Corrected R	
1		14	15							100	100					
2	17	17	16	17					100	100	100	100				
3	17	18	16	15					100	100	100	100				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

Ce document peut être obtenu en français sur demande.

FVS0022-01-(R-06/25)

PRESENT THIS COPY WHEN REGISTERING VEHICLE