04144050

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL VOID WITHOUT
Manitoba
C141058

	DAY	MO.	YR.
Date Inspection Started	03	10	26
Date Inspection Completed	03	10	26
Inspection Expiry Date	31	10	27

Station Number: A5 9 5 1 7 — Station Name: KMTS LTD — City: Vinl

Mechanic Number: M 1 2 1 0 8 — Mechanic Signature: Mike Vel — Station Phone Number: 204 851 2037

Vehicle Owner: 5214165 MB Ltd

Address: Box 441 — City: Souris — Province: MB — Postal Code: R0K 2C0 — Phone:

- [X] Pass/Safe Vehicle
- [ ] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: PBW 1612 — Prov.: MB — NSC #: 0997627 — Odometer Reading: 943815 — Odom. Type: [X] km [ ] mi

Vehicle Identification Number: MBPG5TW73122 — Make: Pet — Model: 389 — Year: 76 — Unit #:

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck — GVWR: 24502 KGS — X Truck Tractor — ____Trailer — ____Semi-Trailer — ____Bus — ____School Bus — ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) — Defects (if any) — Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any) Ref #11) marker light adj/repair
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining (W)		Drum/Rotor (W)		Stroke (W)	
Axle	L	R	L	R	L	R
1	.50	.50	1.71	1.72		
2	.075	.75	16.53	16.53	JR	JR
3	.75	.75	16.53	16.53	JR	JR
4						
5						
	Final Measurement					

32nds Tread Depth — PSI Air Pressure

	Tread Depth Initial				Tread Depth Corrected				Air Pressure Initial				Air Pressure Corrected			
Axle	L		R		L		R		L		R		L		R	
1		11	15							100	100					
2	13	13	15	15					100	100	100	100				
3	11	11	9	9					100	100	100	100				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE