04063793

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL
VOID WITHOUT DECAL

Manitoba C055972

Date Inspection Started: DAY 04 MO. 02 YR. 26
Date Inspection Completed: DAY 04 MO. 02 YR. 26
Inspection Expiry Date: DAY 28 MO. 02 YR. 27

Station Number: A51951 Station Name: KMM J LTD City: Vi
Mechanic Number: M01208 Mechanic Signature: [signature] Station Phone Number: 204557203

Vehicle Owner: 5214165 MB Ltd
Address: Box 441 City: Sanst3 Province: MB Postal Code: R0K2C0 Phone:

[X] Pass/Safe Vehicle
[ ] Fail/Unsafe Vehicle
[ ] Fail/Hazardous

Licence Number: TF61030 Prov.: MB NSC #: 0997627 Odometer Reading: Odom. Type [ ] km [ ] mi
Vehicle Identification Number: 2DEGBSA212R2014574715 Make: Dayton Model: Wagon Year: 24 Unit #:
[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR KGS ___Truck Tractor ___Trailer __X__Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E Circle appropriate Letter for Internal Brake Component Inspection

	Lining IN		Drum/Rotor IN		Stroke IN	
Axle	L	R	L	R	L	R
1	.55	.55	16.57	16.56	1in	1in
2	.55	.60	16.57	16.54	1in	1in
3						
4						
5						
	Final Measurement					

	Tread Depth								Air Pressure							
	Initial 32nds				Corrected				Initial PSI				Corrected			
Axle	L		R		L		R		L		R		L		R	
1	7	8	12	12					100	100	100	100				
2	17	18	10	10					100	100	100	100				
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

Ce document peut être obtenu en français sur demande.

FVS0022-01-(R-06/25)

PRESENT THIS COPY WHEN REGISTERING VEHICLE