04063792

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Ou
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL

Manitoba

C055971

Date Inspection Started: 23 DAY | 02 MO. | 26 YR.
Date Inspection Completed: 24 DAY | 02 MO. | 26 YR.
Inspection Expiry Date: 28 DAY | 02 MO. | 27 YR.

Station Number: A5951 | Station Name: KMMJ LTD | City: Virden
Mechanic Number: M01206 | Mechanic Signature | Station Phone Number: 2048571 2035

Vehicle Owner: 5214165 MB Ltd
Address: Box 441 | City: Souris | Province: MB | Postal Code: R0K2C0 | Phone:

- [X] Pass/Safe Vehicle
- [ ] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: TF61029 | Prov.: MB | NSC #: | Odometer Reading: | Odom. Type: [ ] km [ ] mi

Vehicle Identification Number: 2DEGBSE37R2014571914 | Make: Doepker | Model: Hopper | Year: 24 | Unit #:

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck | GVWR | KGS ___Truck Tractor ___Trailer X Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any) Ref #11 marker light out, replace
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining IN L	Lining IN R	Drum/Rotor IN L	Drum/Rotor IN R	Stroke IN L	Stroke IN R
1	.60	.50	16.56	16.56	1 1/2	1 1/2
2	.65	.50	16.55	16.56	1 1/2	1 1/2
3	.50	.75	16.57	16.57	1 1/2	1 1/2
4						
5						
	Final Measurement					

Axle	Tread Depth Initial 32nds L		Tread Depth Initial 32nds R		Tread Depth Corrected L		Tread Depth Corrected R		Air Pressure Initial PSI L		Air Pressure Initial PSI R		Air Pressure Corrected L		Air Pressure Corrected R	
1	5	5	17	13					100	100	100	100				
2	7	7	11	11					100	100	100	100				
3	5	5	7	9					100	100	100	100				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE