



Annual Inspection Certificate
&
Safety Standards Certificate



VEHICLE INFORMATION

Plate#:	X9493A	Year:	2023
VIN:	1UYVS2533P7818646	Make:	UTILITY TRAILER
GVWR (kg):	29500	Model:	TRAILER
Odometer ():		Type:	Trailer

CERTIFICATE INFORMATION

Annual Inspection Certificate	Expires at the end of: Jul 2026
Safety Standards Certificate	Expires at the end of: August 10, 2025
Vehicle Inspection Certificate Number	H1T0AB04
Inspection Start Date	Jul 5, 2025 System Time: 17 : 28
Inspection End Date	Jul 5, 2025 System Time: 00 : 18

VEHICLE INSPECTION CENTRE

Vehicle Inspection Centre #: 11378	Technician: PREET DEOL
FLEET CARE INC.	
O/A FLEET CARE INC.	
273 GLIDDEN RD #1, BRAMPTON, ON	
BRAMPTON, ON L6W1H9	Technician Signature
647-308-0037	Technician ID: 103094
	STO ID/Account: 19013885
	Trade Code: 310T

I certify that I inspected this vehicle on the inspection date in accordance with the inspection procedures established by directive under s. 100.7 of the Highway Traffic Act and that the vehicle meets the required equipment and performance standards as detailed in the Vehicle Inspection Report with the above referenced Vehicle Inspection Certificate Number.

This Certificate is not a warranty on the condition of the vehicle.

Vehicle Inspection Questions?

Call the Public Contact Centre 1-833-420-2103 or go to

<https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program>.

MINISTRY OF TRANSPORTATION
SAFETY INSPECTION REPORT



Vehicle Inspection Certificate Number: H1T0AB04

Start Date / Time: Jul 5, 2025, 5:28 PM

End Date / Time: Jul 5, 2025, 8:18 PM

VEHICLE/ENGINE INFORMATION

CHASSIS

Plate#: X9493A

Year: 2023

VIN: 1UYVS2533P7818646

Make: UTILITY TRAILER

GVWR(kg): 29500

Model: TRAILER

Odometer:

Fleet ID: 11378

SAFETY INSPECTION RESULT

PASS

SAFETY SYSTEM INSPECTION RESULTS

All Safety System Components Passed Inspection

MANDATORY ITEMS

Inspection Item	Result
Axle 1, Driver Side, Inner Tire	
Tire Tread Depth (mm)	5
Initial Tire Pressure (kPa)	725
Axle 1, Driver Side, Outer Tire	
Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	725
Drum Brakes	
Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	11
Drum Inside Diameter (mm)	419.26
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	32

Inspection Item	Result
Axle 1, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	5
Initial Tire Pressure (kPa)	725
Axle 1, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	725
Drum Brakes	
Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	11
Drum Inside Diameter (mm)	419.24
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	32

Inspection Item	Result
Axle 2, Driver Side, Inner Tire	
Tire Tread Depth (mm)	12
Initial Tire Pressure (kPa)	725
Axle 2, Driver Side, Outer Tire	

Inspection Item	Result
Axle 2, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	725
Axle 2, Passenger Side, Outer Tire	

Drum Brakes	
Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	9
Drum Inside Diameter (mm)	419.14
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	32

Drum Brakes	
Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	8
Drum Inside Diameter (mm)	419.22
Within OEM specifications?	Yes
S-Cam Drum Brakes	
Chamber Type (size)	30
Brake Stroke (mm)	32

Vehicle Inspection Centre #: 11378	Technician #: 103094
FLEET CARE INC.	Name: PREET DEOL
273 GLIDDEN RD #1, BRAMPTON, ON	Report Number: 4
BRAMPTON, ON L6W1H9	Tablet ID: 13306
647-308-0037	STO ID/Account: 19013885
Software Version: 2024.08.21.1	Trade Code: 310T

Vehicle Inspection Questions? Call the Public Contact Centre 1-833-420-2103 or go to <https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program>