

FACILITY:	NORTHERN B.C. TRUCKERS' / N5398	INSP. TYPE:	Complete	INSP. START:	2026-Jan-13 06:00 AM MST
INSPECTOR:	CHRISTIANSON, LESLIE RYAN / 106407	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Jan-13 07:30 AM MST
WORK ORDER #:		INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	10690072	VIN:	5KJRALBG6DPFG8932
PLATE #:	Et8077	UNIT/FLEET#:	20509	OWNER/LESSEE NAME:	J Bueckert logging ltd. .
LICENCED GVW(kg):	63500	BODY STYLE:	Truck Tractor	ADDRESS:	11706 Maclean rd
VEHICLE YEAR:	2013	ODOMETER:	207501 KM		Fort St John, British Columbia
MAKE:	WESTERN ST	HUB ODOMETER:			V1j8b3, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Lt repaired
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) New window
Section 9A - Tires	Passed Recent drives and l1
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed Recent 5 th wheel rebuild kit
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	31	32
2	Clamp	30L	Automatic	36	39
3	Clamp	30L	Automatic	38	35
4	Clamp	30L	Automatic	37	38
Comment:					

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
15			13	✓
21	21	21	21	
21	21	21	21	
21	21	21	21	
Comment:				

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

1/13/2026 8:38:59 AM MST

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	55	35	Lining (Shoe)	17	19	Drum		
2	58	34	Lining (Shoe)	17	19	Drum		
3	60	35	Lining (Shoe)	16	19	Drum		
4	62	47	Lining (Shoe)	16	18	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
Has this Vehicle been road tested? No

Road Test Date:
Road Tester:
Inspector: CHRISTIANSON, LESLIE RYAN

Signature:


This Inspection Report was submitted to CVSE on 2026-Jan-13 08:38 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

1/13/2026 8:38:59 AM MST