



# Commercial Vehicle Inspection Report

Decal Number: PA11176  
Decal Expiry Date: 2026-Nov-30  
Inspection Number: 21762959

Inspection Result:  
**PASS**

**FACILITY:** NORTHERN B.C. TRUCKERS' / N5398  
**INSPECTOR:** CHRISTIANSON, LESLIE RYAN / 106407  
**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Semi-annual  
**INSP. START:** 2026-May-06 01:15 PM MST  
**INSP. COMPLETE:** 2026-May-06 02:15 PM MST

**WORK ORDER #:**

**VEHICLE JUR:** British Columbia  
**PLATE #:** 48381C  
**LICENCED GVW(kg):** 999999  
**VEHICLE YEAR:** 2007  
**MAKE:** DOEPKER  
**MODEL:**  
**REGI:** 03810448  
**UNIT/FLEET#:** 216  
**BODY STYLE:** LOGGING TRAILER  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**  
**VIN:** 2DELGFZ3671019061  
**OWNER/LESSEE NAME:** J Bueckert logging ltd. .  
**ADDRESS:** 11706 Maclean rd  
Fort St John, British Columbia  
V1j8b3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed Recent brake work
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) Rt tail and markers Abs light replacement
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) Axle 1 tires r3 r2 tire
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

**Air Brake Chamber Type, Size and Push Rod Stroke (mm)**

Axles	Type	Size	Slack Adj.	Left	Right
1	Bolt	A	Not Applicable		
2	Bolt	A	Not Applicable		
3	Bolt	A	Not Applicable		
<b>Comment:</b>					

**Tire Tread Depth (mm)**

Outer L	Inner L	Inner R	Outer R	Steering
13	13	13	12	
10	13	10	11	
13	12	13	13	
<b>Comment:</b>				

**Air Brake Camshaft Rotation (degrees)**

Axles	Left	Right
1		
2		
3		
<b>Comment:</b>		

**Brake Lining/Pad (mm)**

Lining/Pad	Left	Right
Lining (Shoe)	10	15
Lining (Shoe)	20	15
Lining (Shoe)	19	18
<b>Comment:</b>		

**Rotor Thickness or Drum Inside Diameter (mm)**

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		
<b>Comment:</b> Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

**Inspection Comments:**

Has this Vehicle been road tested? No  
Inspector: CHRISTIANSON, LESLIE RYAN

Road Test Date:  
Signature: 

Road Tester:

This Inspection Report was submitted to CVSE on 2026-May-06 03:43 PM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/6/2026 3:43:52 PM MST