



Commercial Vehicle Inspection Report

Decal Number: PY25981
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21627612

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN / 106407
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-Jan-13 07:30 AM MST
INSP. COMPLETE: 2026-Jan-13 08:30 AM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: 35979B
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2005
MAKE: SUPERIOR
MODEL:
REGI: 02992852
UNIT/FLEET#: 211
BODY STYLE: LOGGING TRAILER
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2S9SB51365T008104
OWNER/LESSEE NAME: J Bueckert logging ltd, .
ADDRESS: 11706 Maclean rd
Fort St John, British Columbia
V1j6b3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	33
2	Clamp	30	Automatic	34	39
3	Clamp	30	Automatic	38	36

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
13	13	6	8	
11	11	12	13	
13	13	10	11	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	73	71
2	79	31
3	74	78

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	13	15
Lining (Shoe)	14	19
Lining (Shoe)	11	11

Comment:


Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: CHRISTIANSON, LESLIE RYAN

Road Test Date:
Signature: 

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jan-13 08:58 AM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014
1/13/2026 8:58:19 AM MST