



Commercial Vehicle Inspection Report

Decal Number: PA11200
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21767211

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: CHRISTIANSON, LESLIE RYAN / 106407
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-May-09 04:00 PM MST
INSP. COMPLETE: 2026-May-09 05:00 PM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2003
MAKE: DOEPKER
MODEL:
REGI: 01177392
UNIT/FLEET#: 212
BODY STYLE: LOGGING TRAILER
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2DELGFZ3731015014
OWNER/LESSEE NAME: J Bueckert logging ltd. .
ADDRESS: 11706 Maclean rd
Fort St John, British Columbia
V1j8b3, Canada

| | |
|--|--|
| Vehicle Identification (VIN) | Passed |
| Section 1 - Power Train | Not Applicable |
| Section 2 - Suspension | Passed |
| Section 3 - Brake System | Repaired (same day) Abs repair |
| Section 3A - Air Brakes | Passed Recent brake work |
| Section 3H - Hydraulic Brakes | Not Applicable |
| Section 4 - Steering | Not Applicable |
| Section 5 - Instruments and Auxiliary Equipment | Not Applicable |
| Section 6 - Lamps | Repaired (same day) Light replace 2 |
| Section 7 - Electrical System | Passed |
| Section 8 - Frame and Body | Passed |
| Section 9A - Tires | Repaired (same day) Two tires |
| Section 9B - Wheels | Passed |
| Section 10 - Coupling Devices | Passed |
| Section 11 - Other Vehicle Components | Not Applicable |

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

| Axles | Type | Size | Slack Adj. | Left | Right |
|-----------------|-------|------|------------|------|-------|
| 1 | Clamp | 30 | Automatic | 37 | 36 |
| 2 | Clamp | 30 | Automatic | 35 | 38 |
| 3 | Clamp | 30 | Automatic | 39 | 37 |
| Comment: | | | | | |

Tire Tread Depth (mm)

| Outer L | Inner L | Inner R | Outer R | Steering |
|-----------------|---------|---------|---------|----------|
| 12 | 13 | 12 | 12 | |
| 13 | 12 | 11 | 18 | |
| 11 | 12 | 13 | 9 | |
| Comment: | | | | |

Air Brake Camshaft Rotation (degrees)

| Axles | Left | Right |
|-----------------|------|-------|
| 1 | 35 | 48 |
| 2 | 35 | 90 |
| 3 | 58 | 62 |
| Comment: | | |

Brake Lining/Pad (mm)

| Lining/Pad | Left | Right |
|-----------------|------|-------|
| Lining (Shoe) | 19 | 18 |
| Lining (Shoe) | 19 | 12 |
| Lining (Shoe) | 17 | 16 |
| Comment: | | |

Rotor Thickness or Drum Inside Diameter (mm)

| Rotor/Drum | Left | Right |
|---|------|-------|
| Drum | | |
| Drum | | |
| Drum | | |
| Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured. | | |

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: CHRISTIANSON, LESLIE RYAN

Road Test Date:
Signature: 

Road Tester:

This Inspection Report was submitted to CVSE on 2026-May-09 06:40 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/9/2026 6:40:59 PM MST