04144053

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL VOID WITHOUT DECAL

Manitoba C141061

	DAY	MO.	YR.
Date Inspection Started	04	09	26
Date Inspection Completed	04	10	26
Inspection Expiry Date	31	10	27

Station Number: A5 19 5 1 — Station Name: KMMJ LTD — City: Virden

Mechanic Number: M0 12 10 8 — Mechanic Signature: [signature] — Station Phone Number: 204 855 2038

Vehicle Owner: 5214165 MB Ltd

Address: Box 441 — City: Sanis — Province: MB — Postal Code: R0K 2E0 — Phone:

- [X] Pass/Safe Vehicle
- [ ] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: CRW959 — Prov.: MB — NSC #: 077627 — Odometer Reading: 794874 — Odom. Type: [X] km [ ] mi

Vehicle Identification Number: 1XPBXD49X7RD673279 — Make: Pete — Model: 389 — Year: 24 — Unit #:

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR 24500 KGS ___X___Truck Tractor ____Trailer ____Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining IW		Drum/Rotor IW		Stroke IW	
Axle	L	R	L	R	L	R
1	.70	.70	16.52	16.52	IA	IA
2	.75	.75	16.52	16.52	IA	IA
3	.75	.75	16.52	16.52	IA	IA
4						
5						
	Final Measurement					

	Tread Depth								Air Pressure							
	Initial 32nds				Corrected				Initial PSI				Corrected			
Axle	L		R		L		R		L		R		L		R	
1		11	14							100	100					
2	18	17	18	17					100	100	100	100				
3	14	16	12	13					100	100	100	100				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE